

Report ID: 18,271,557 Version: 1 Created: 01 Aug 2018

Make:	Suzuki	Model:	Splash	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2,009	Registration:		Reg Expiry:		Engine			L
WoF Expiry:		Odometer:	82,716 Kms	Good No:	18271557	Oil level	~		
VIN:	TSMEXB32S00293093	Next Service:		Service Histor		Smoke & fumes	~		
			<i>2</i> , 2, 2, 2, 2, 2, 2, 2, 2, 2, 2, 2, 2, 2,			Performance	~		
	port is not a warranty		с I I		1 B 41 1	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
						Performance	~		
Key:		-0		-161-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			L
D = dent	- HE			The		Operation	~		
R = rust PT = paint defe				\prod	JHIH	Noise	~		
C = crack						Clutch	•		~
P = pin dent					세비	CV joints	~		
* = decals	616			-NL	ELLEN	Wheel bearings	~		
SC = stone chips						Brakes			
W = significan	t scuffs	$- \emptyset$				Performance	~		
		Note: son	ne defects & blemishes	mav not be disc	laved in the diagram	Hand Brake	~		
Body Insp	pection Comments			,	.,	Tyres (lowest observed tread	-	of tyre	 (کد
									mm
						Right front	3		 mm
						Left rear			mm
Conditions During Rody Inspection:						Right rear			 mm
Conditions During Body Inspection: Dry						Spare			
Under Carriage & Under Bonnet Inspection Comments						Spare Yes Suspension			
Tidy .	-	•				Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Jeals						Tail lights	~		
Carpets	Good					Indicators	~		
Denela	Good					Dashboard warning lights	~		
Panels						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
						Window winder FE	~		
General Comments						Window winder RL	~		
Nice little hatch .						Window winder RE	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	· ·		L
Road Conditions During Test Drive: Drv						Central locking	2		
Koad Con	aitions During Tes	t Drive:	Dry			Remote locking	~ ~		
Engine Tir	ming Mechanism:	Timing	Chain			Sat. Nav. (basic test only)	~		
Evidence of Cam Belt Replacement: Not Applicable Kms:									v
		- ···· ľ				Reversing camera			~
Inspected by: Daryll Timms Date: 01 Aug 2018									

I have read and understood this condition guide.

Name:

Signature: