

Report ID: 18,271,831 Version: 1 25 Jul 2018 Created:

Make:	Mitsubishi	Model:	Challenger	Body Style:	Wagon		Pass	Fail	N/A
Year:	1,998	Registration:	AGK851	Reg Expiry:	24 Oct 2018	Engine			L
WoF Expiry:	,	Odometer:	190,175 Kms	Good No:	18271831	Oil level	~		<u> </u>
VIN:	7A8CJ2W0701102088		Just serviced	Service Histor		Smoke & fumes	~		
	7865200701102000		5431 301 1024		. 110	Performance	~		
	port is not a warranty					Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition			
		_				Performance	~		
Key:	sc	-0	L SC			Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent				JAC U	HID SW				<u> </u>
R = rust				10		Operation	~		
PT = paint def	ect	-		+		Noise Clutch	~		<u> </u>
C = crack P = pin dent	Ho			-					~
* = decals	sc w DC				ANR -	CV joints	~		
SC = stone chips						Wheel bearings	~		
W = significant scuffs SC W W W						Brakes			
						Performance	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~	6 .	Ļ
						Tyres (lowest observed tread	d depth T	of tyre	-
						Left front	2.0 mm		
						Right front	2	.0	mm
						Left rear	2	.0	mm
Conditions During Body Inspection: Wet						Right rear	2	.0	mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
minor Oil le	ak engine					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
Carpets	Average					Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	Average					Wipers (front & rear)	~		
Dashboa						Window winder FL	~		
	_					Window winder FR	~		
<u>General (</u>	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		•
Road Conditions During Test Drive: Wet						Central locking	~		
	-					Remote locking		~	
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	10	Kms:		Reversing camera			~
Inspected by: Dion Mair Date: 13 Jul 2018									
I have read	and understood th	is condition o	juide. Name:			Signature:			