

Report ID: 55,606


Version: 1

Created: 21 Jul 2018

| Make: | Subaru | Model: | Outback | Body Style: | SUV |
|-------------|-------------------|---------------|---------------|----------------------|-------------|
| Year: | 2,009 | Registration: | FCD783 | Reg Expiry: | 07 Sep 2018 |
| WoF Expiry: | 26 Jul 2019 | Odometer: | 195,386 Kms | Good No: | 18271883 |
| VIN: | 7A8GF160709004669 | Next Service: | Just Serviced | Service History: Yes | |

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection:

Under Carriage & Under Bonnet Inspection Comments

| Interior Comments | | | | | |
|-------------------|------|--|--|--|--|
| Seats | GOOD | | | | |
| Carpets | GOOD | | | | |
| Panels | GOOD | | | | |
| Dashboard | GOOD | | | | |

Dry

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt **Evidence of Cam Belt Replacement:**

No

Kms:

Inspected by: **JAMES**

| l | | Pass | Fail | N/A |
|--------|------------------------------|---|---------|-----|
| l | Engine | | | |
| l | Oil level | ~ | | |
| | Smoke & fumes | ~ | | |
| 1 | Performance | VVV | | |
| l | Noise | ~ | | |
| l | Cooling System | | | |
| J | Coolant condition | ~ | | |
| 1 | Performance | V | | |
| | Radiator / Hoses (visual) | ~ | | |
| ı | Transmission | | | |
| | Operation | ~ | | |
| l | Noise | ~ | | |
| | Clutch | | | ~ |
| l | CV joints | ~ | | |
| | Wheel bearings | ~ | | |
| | Brakes | | • | |
| l | Performance | ~ | | |
| | Hand Brake | ~ | | |
| l | Tyres (lowest observed tread | depth | of tyre | es) |
| | Left front | 4 | .0 | mm |
| l | Right front | 4.0 | | mm |
| J | Left rear | 4.0 | | mm |
| 1 | Right rear | 4.0 | | mm |
| , 1 | Spare | | Yes | |
| l | Suspension | | | |
| | Suspension performance | ~ | | |
| | Steering performance | ~ | | |
| l | Shock absorbers | ~ | | |
| l | Air Conditioning / Heater | | | |
| 1 | Operation | ~ | | |
| | Electrical / Accessories | | | |
| | Head lights | ' | | |
| | Tail lights | > | | |
| | Indicators | \(\triangle \) | | |
| | Dashboard warning lights | ~ | | |
| l | Wipers (front & rear) | ~ | | |
| | Window winder FL | ~ | | |
| , 1 | Window winder FR | ~ | | |
| | Window winder RL | ンン | | |
| | Window winder RR | ~ | | |
| l | Rear view mirrors | ~ | | |
| l | Radio (basic test only) | ~ | | |
| | CD (basic test only) | / | | |
|] | Number of keys | 2 | | |
|] | Central locking | ~ | | |
|] | Remote locking | ~ | | |
| | Sat. Nav. (basic test only) | | | ~ |
| | Reversing camera | | | ~ |
| _ | D | 0 | | |
| | Date: 13 Jul 201 | X | | |

I have read and understood this condition guide.

Name:

Signature: