

Basic Vehicle Condition Guide

Report ID: 18,272,273


Version:

Created: 11 Jul 2018

Make: Model: Mitsubishi Mirage **Body Style:** Hatchback Year: 2,014 Registration: HMN576 Reg Expiry: 02 Oct 2018 WoF Expiry: **Odometer:** 27 Jun 2019 **Good No:** 18272273 42,008 Kms VIN: MMAXTA03AEH01606 Next Service: Service History: 55000 Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions I	Durina	ı Body	Inspection:	Drv

Under Carriage & Under Bonnet Inspection Comments

Interior Comments	<u>5</u>
Seats	Good
Carpets	Good
Panels	Good
Dashboard	Good

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: John Lindsay Date: 11 Jul 2018

Name:

	Pass	Fail	N/A
Engine			1
Oil level	~		
Smoke & fumes	\(\times \)		
Performance	~		
Noise	~		
Cooling System		,	
Coolant condition	~		
Performance	<i>V V</i>		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed treac	depth	of tyre	es)
Left front	6	5	mm
Right front	6	5	mm
Left rear	7	7	mm
Right rear	7	7	mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	V V		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	V V V V V V		
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	2		
Central locking	~		
Remote locking	-		
Sat. Nav. (basic test only)			~
Reversing camera			

Signature: