

Basic Vehicle Condition Guide

Report ID: 18,273,043


Version: 1

Created: 11 Jul 2018

Make: Model: Ford Territory **Body Style:** SUV Year: 2,005 Registration: Reg Expiry: LLG54 31 Aug 2018 **WoF Expiry: Odometer:** 20 Jun 2019 **Good No:** 18273043 136,900 Kms VIN: **Next Service: Service History:** 6FPAAAJGAT5A86002 151000 Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Dion Mair Date: 10 Jul 2018

Name:

	_	_	_
	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	<i>y y</i>		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	<i>v</i>		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	d depth	of tyre	es)
Left front	3	.0	mm
Right front	3.0		mm
Left rear	3	.0	mm
Right rear	3.0		mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			1
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	\(\triangle \)		
Wipers (front & rear)	<i>v</i>		
Window winder FL	~		
Window winder FR	1		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	2	l	-
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			'
Reversing camera			~

Signature: