

Report ID: 18,273,223 Version: 1 Created: 23 Jul 2018

Make:	Toyota	Model:	lsis	Body Style:	SUV		Pass	Fail	N/A
Year:	2,005	Registration:	-	Reg Expiry:	-	Engine	1	I	L
	05 Jul 2019	Odometer:	80,155 Kms	Good No:	18273223	Oil level	~		
VIN:	7AT0H658X18032675	Next Service:	90,151kms	Service Histor		Smoke & fumes	v		
			50,1511		,	Performance	~		
	port is not a warranty		с I II			Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						•			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition			
						Performance	~		
Key:		-0				Radiator / Hoses (visual)	~		
S = scratch						Transmission	Sual)		
D = dent	- Alle			1 - L	EIU -	Operation	~		
R = rust				10	THIA	Noise	~		
PT = paint defe C = crack	ect M			$\square \cup$		Clutch	~		~
P = pin dent	Ho					CV joints	~		
* = decals	- MIK			AL-	ETTR	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs						Performance			
		Note: con	Ledefects & blemishes	may not be disr	layed in the diagram	Hand Brake	レ レ		
Body Insp	pection Comments	1016.301	le delects & blemisnes	may not be disp	hayed in the diagram		•	~ f t	
						Tyres (lowest observed tread depth of tyres)			
						Left front	5		mm
						Right front	5		mm
						Left rear	5 mm		-
Conditions During Body Inspection: Wet						Right rear	4 mm		
Under Carriage & Under Bonnet Inspection Comments					Spare	Yes			
						Suspension			
Tidy .						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
Good						Electrical / Accessories			
Seats	Good					Head lights	~		ļ
Carpets	Good					Tail lights	~		
	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	Good					Wipers (front & rear)	~		
						Window winder FL	~		
						Window winder FR	~		
<u>General Comments</u> Good 7 seater wagon .						Window winder RL	~		
GOOU / Sea	ter wagon.					Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Wet						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test only)									~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Daryll Timms Date: 23 Jul 2018									
Inspected by. Daryii fininis Date: 23 Jul 2018									

I have read and understood this condition guide.

Name:

Signature: