

Report ID: 18,273,920 Version: 1 23 Jul 2018 Created:

Make:	Suzuki	Model:	Swift	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2,009	Registration:		Reg Expiry:		Engine	I	<u> </u>	1
WoF Expiry:		Odometer:	68,842 Kms	Good No:	18273920	Oil level	~		
VIN:	7AT0GK0CX18476256	Next Service:	78,838kms	Service History	V: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	oration is made	for and milago	Darts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		1
						Performance	~		
Key:		-0		-01-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	- HE			TIN		Operation	~		
R = rust PT = paint def				$\left(\left \right\rangle \right)$		Noise	~		
C = crack				+		Clutch			~
P = pin dent	HIG				74 <u>11</u>	CV joints	~		
* = decals	616		<u> </u>	The	HIP	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs						Performance	~		
		Note: son	ne defects & blemishes	may not be disp	laved in the diagram	Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Tyres (lowest observed tread	•		
						Left front 3 mm			
						Right front		3	mm
						Left rear			mm
						Right rear	5		mm
Conditions During Body Inspection: Wet						Spare	-		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes Yes			
OK.						Suspension performance	~		1
						Steering performance	~		
						Shock absorbers	~		-
						Air Conditioning / Heater	V		
						Operation	~		1
Interior Comments						Electrical / Accessories			
Good						Head lights	~		1
Seats						Tail lights	<i>v</i> <i>v</i>		
Carpets	Good								
Dev. 1	Good					Indicators	V 		
Panels						Dashboard warning lights Wipers (front & rear)	v		──
Dashboa	rd Good					Window winder FL	v		
						Window winder FL Window winder FR	V 		
General (<u>Comments</u>						V 		
Good little hatch .						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	v		
						Radio (basic test only)	~		
						CD (basic test only)	v		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		<u> </u>
Engine Timing Mechanism: Timing Chain						Remote locking	~		
						Sat. Nav. (basic test only)			~
Lviuence			lot Applicable	11115.		Reversing camera			~
Inspected by: Daryll Timms Date: 23 Jul 2018									

I have read and understood this condition guide.

Name:

Signature: