

Report ID: 18,273,954 Version: 1 23 Jul 2018 Created:

Make:	Toyota	Model:	Regius	Body Style:	Van		Pass	Fail	N/A
Year:	2,013	Registration:		Reg Expiry:		Engine	1		L
WoF Expiry:	10 Jul 2019	Odometer:	125,096 Kms	Good No:	18273954	Oil level	~		
VIN:	7AT0H63TX18011328	Next Service:	135,000kms	Service Histor		Smoke & fumes	~		
						Performance	~		
	port is not a warranty		с I I	D		Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
						Performance	~		
Key:		-0				Radiator / Hoses (visual)	~		
S = scratch							Transmission		
D = dent	- Alle			The		Operation	~		
R = rust				10	JHIN	Noise	~		
PT = paint defe C = crack	ect M			+		Clutch	V		
P = pin dent	Ho				JUII —	CV joints			~
* = decals	- MIK			AL-	ENR -	Wheel bearings			~
SC = stone chi	ps US	VA		10			~		
W = significant scuffs						Brakes			
		N			Leve d'in the alle survey	Performance	~		
Body Insp	pection Comments	Note: som	ne defects & blemishes	may not be disp	blayed in the diagram	Hand Brake	~		
					Tyres (lowest observed tread depth of tyres)				
						Left front	5	5	mm
						Right front	5	5	mm
						Left rear	4	1	mm
Conditions During Body Inspection: Wet						Right rear	5 mm		
						Spare	are Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Tidy .						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Commonte						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Correcto	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	Good					Wipers (front & rear)	~		
Dashboa	ra					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL			~
Good van.						Window winder RR			~
						Rear view mirrors			~
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		L
Road Conditions During Test Drive: Wet						Central locking	~		
			VVCL			Remote locking	~		
Engine Tir	ming Mechanism:	Cambelt	t			Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Yes Kms: 99,577						Reversing camera			~
						-	I		
Inspected by: Daryll Timms Date: 23 Jul 2018									

I have read and understood this condition guide.

Name:

Signature: