

Basic Vehicle Condition Guide

Report ID: 18,274,634

Version: 1

Created: 17 Jul 2018


Make:HondaModel:CRVBody Style:SUVYear:2,005Registration:Reg Expiry:

 WoF Expiry:
 10 Jul 2019
 Odometer:
 124,514 Kms
 Good No:
 18274634

 VIN:
 7AT08G7HX18001813
 Next Service:
 134000
 Service History:
 No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Bobby Zhong Date: 17 Jul 2018

Name:

	Pass	Fail	N/A	
Engine			1	
Oil level	~			
Smoke & fumes	\(\times \)			
Performance	~			
Noise	~			
Cooling System				
Coolant condition	~			
Performance	~			
Radiator / Hoses (visual)	~			
Transmission				
Operation	~			
Noise	~			
Clutch			~	
CV joints	~			
Wheel bearings	~			
Brakes				
Performance	~			
Hand Brake	~			
Tyres (lowest observed tread depth of tyres)				
Left front		5	mm	
Right front		5	mm	
Left rear		5	mm	
Right rear	5		mm	
Spare		Yes		
Suspension				
Suspension performance	~			
Steering performance	V V			
Shock absorbers	~			
Air Conditioning / Heater				
Operation	~			
Electrical / Accessories				
Head lights	~			
Tail lights	~			
Indicators	~			
Dashboard warning lights	~			
Wipers (front & rear)	V V V V V V			
Window winder FL	~			
Window winder FR	~			
Window winder RL	~			
Window winder RR	~			
Rear view mirrors				
Radio (basic test only)	'			
CD (basic test only)	~			
Number of keys	2			
Central locking	•			
Remote locking	~			
Sat. Nav. (basic test only)			'	
Reversing camera				

Signature: