

Report ID: 18,274,718 Version: 1 Created: 09 Aug 2018

Make:	Toyota	Model:	Landcruiser	Body Style:	Wagon		Pass	Fail	N/A
Year:	1,995	Registration:	KTH521	Reg Expiry:	22 Jul 2018	Engine			
WoF Expiry:	04 Jan 2019	Odometer:	428,589 Kms	Good No:	18274718	Oil level	~		
VIN:	7A8H60H0705052000	Next Service:	438000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
						Performance	~		
Key:	S SC	-0	s sc sc	-01-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust PT = paint defect						Operation	~		
						Noise	~		
C = crack						Clutch	~		
P = pin dent						CV joints	~		
* = decals SSC 919						Wheel bearings	~		
SC = stone chips						Brakes	•		
W = significant scuffs SC SW						Performance	~		1
Note: come defects & blamiches may not be displayed in the diagram						Hand Brake	~		
Body inspection Comments						Tyres (lowest observed treat	•	ofture	
Aerial broken ,LR tail light cracked ,						Left front			
								7	mm
						Right front Left rear		7	mm
								7	mm
Conditions During Body Inspection: Dry						Right rear	7	7	mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
		meenspeen				Suspension			1
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			Т
Interior Comments						Operation		~	
Average						Electrical / Accessories			
Seats	Average					Head lights	~		
Carpets	Average					Tail lights	~		
						Indicators	~		
Panels	middle co	nsole modified ,				Dashboard warning lights	~		
Dashboa	stuff attac	hed to the dash ,	,			Wipers (front & rear)	~		
						Window winder FL	~		
						Window winder FR	~		
<u>General Comments</u>					Window winder RL	~			
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		•
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking			~
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	10	Kms:		Reversing camera			~
						L	. <u> </u>		
Inspected by: Donovan Matara Date: 09 Aug 2018									
I have read and understood this condition guide. Name:									