

Report ID: 18,275,006 Version: 1 20 Jul 2018 Created:

Make:	Ford	Model:	Focus	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2,012	Registration:	GMW762	Reg Expiry:	05 Dec 2018	Engine	I		
WoF Expiry:		Odometer:	87,170 Kms	Good No:	18275006	Oil level	~		<u> </u>
VIN:	MPB1XXMXB1CK0135	Next Service:	96000	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for ago and miloago	Parts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechar	ical inspection prior to	purchase and tl	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
						Performance	~		
Key:	SD W	-0		-161-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	s sc			10	EIU/	Operation	~		
R = rust PT = paint def				\prod		Noise	~		
C = crack						Clutch			~
P = pin dent						CV joints	~		
* = decals	- PIK			AL.	EITR	Wheel bearings	~		
SC = stone chips						Brakes	V		
W = significant scuffs						Performance	~		1
		Nataron	ne defects & blemishes	may not be disr		Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							-	ofture	
						Tyres (lowest observed tread depth of tyres)			-
						Left front	4		mm
						Right front		ł	mm
						Left rear	4		mm
Conditions During Body Inspection: Wet						Right rear	4 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
	mage & onder bor	mermspectic	<u>on comments</u>			Suspension	L .		1
Tidy						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	1		Т
Interior Comments						Operation	~		
Good						Electrical / Accessories			T
Seats	Good					Head lights	~		
Carpets	Good					Tail lights	~		
curpets	Card					Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
Dastibua						Window winder FL	~		
						Window winder FR	~		
<u>General (</u>	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Con	ditions During Test	t Drive:	Wet			Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	10	Kms:		Reversing camera			~
с						L	I		
Inspected by: Stuart Melbourne Date: 20 Jul 2018									
I have read	and understood th	is condition a	guide. Name: .			Signature:			