

Report ID: 18,275,132 Version: 1 12 Jul 2018 Created:

Make:	Mazda	Model:	Axela	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2,004	Registration:	EWS513	Reg Expiry:	05 Mar 2018	Engine	1		1
WoF Expiry:	19 Apr 2018	Odometer:	227,978 Kms	Good No:	18275132	Oil level		~	
VIN:	7A8C13J0708104664	Next Service:	0	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	r an additional c	harge.	Coolant condition	~		
						Performance	V		
Key:	S SC	-0	S D SC S P SC		S P SC	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	s sc			The	FILL S	Operation	~		
R = rust PT = paint defe				\prod		Noise	~		
C = crack						Clutch			~
P = pin dent	-110				세비	CV joints	~		•
* = decals	ssc 919			The	HIP	Wheel bearings	v		
SC = stone chips						Brakes			
W = significant scuffs S SC S S S S S S S S S S S S S S S S S						Performance	~		
		Note: som	ne defects & blemishes	may not be disp	laved in the diagram	Hand Brake	~		
Body Insp	pection Comments				,	Tyres (lowest observed tread		of tyre	() ()
					Left front 6 mm				
						Right front			mm
						Left rear			mm
						Right rear	6	-	
Conditions During Body Inspection: Wet						Spare	3 mm		
Under Carriage & Under Bonnet Inspection Comments						Suspension	165		
Minor oil le	-					Suspension performance	~		
	,					Steering performance	~		
						Shock absorbers	~		
							V		
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
Seats							~		
Carpets	Average					Tail lights	~		
	Average					Indicators	~		
Panels						Dashboard warning lights	~		
Dashboa	rd Average					Wipers (front & rear)	~		
						Window winder FL	~		
General	Comments					Window winder FR	~		
	<u>comments</u>					Window winder RL	~		
						Window winder RR		~	
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Con	ditions During Test	t Drive:	Wet			Central locking	~		
Engine Ti	ming Mechanism	Time in a f	Chain			Remote locking	~		
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
Evidence		ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Donovan Matara Date: 12 Jul 2018									

I have read and understood this condition guide.

Name:

Signature: