



Turners Certified Imports 50 Point Check

Report ID: 18,275,227

Version: 2

Created: 30 Oct 2018

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Make: Toyota Body Style: Hatchback
Model: Blade Odometer: 50,747 Kms
Year: 2007 VIN: 7AT0H656X18021348

Under Carriage & Under Bonnet Inspection CommentsGeneral Comments

Seats: Good

Carpets: Good

Panels: Good

Dashboard: Good

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable

Replaced At (odometer reading):

Road Conditions During Test Drive: Wet

Electrical

Battery ☒
Head lights ☒
Tail lights ☒
Indicators ☒
Dashboard warning lights ☒
Wipers (front & rear) ☒
Window winder FL ☒
Window winder FR ☒
Window winder RL ☒
Window winder RR ☒
Rear view mirrors ☒
Radio (basic test only) ☒
CD (basic test only) ☒
Reversing camera ☒

Transmission & Drive

Operation ☒
Noise ☒
Clutch ☐
CV joints ☒
Wheel bearings ☒
Wheel balance ☒

Brakes

Performance ☒
Hand Brake ☒

Keys & Locking

Central locking ☒
Remote locking ☒
Number of keys

Engine

Oil level ☒
Smoke & fumes ☒
Performance ☒
Noise ☒

Cooling System

Coolant condition ☒
Performance ☒
Radiator / Hoses (visual) ☒

Suspension

Suspension performance ☒
Steering performance ☒
Shock absorbers ☒

Tyres (lowest observed tread depth)

Left front mm
Right front mm
Left rear mm
Right rear mm
Spare
Tools ☐

Interior

AC Operation ☒
Heater fan ☐
Seatbelts ☒
Horn ☒

Turners Certified Key

✓ = Pass X = Fail
• = Not applicable for this vehicle

Inspected by: Roger King

Date: 30 Oct 2018

I have read and understood this condition guide.

Name:

Signature: