

Basic Vehicle Condition Guide

Report ID: 18,275,987

Version: 3


Created: 29 Aug 2018

Fail N/A

Make: Model: **Body Style:** Hatchback Ford Fiesta Year: 2,004 Registration: Reg Expiry: FZM909 06 Apr 2019 WoF Expiry: **Odometer: Good No:** 18275987 30 Apr 2019 173,364 Kms VIN: WF0HXXWPJH4A6251 **Next Service: Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Holes on rear bumper Fuel lid lock need attention, not locking Bonnet lock not releasing, lever missing RL door window side trim missing Interior mirror need attention

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Interior Comments Seats Average Carpets Average Panels Average Dashboard Good

General Comments

Inspected by:

EAC fail warning on, engine idle RPM high AC not working Gear shift slider cover missing

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No

Kms:

Engine			
Oil level	~		
Smoke & fumes	~		
Performance		~	
Noise		~	
Cooling System		•	
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes		•	
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	d dept	h of tyr	es)
Left front		2.0	mm
Right front		3.0	mm
Left rear		3.0	mm
Right rear		3.0	mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater		•	
Operation		~	
Electrical / Accessories	•	•	•
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights		~	
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)		~	
Number of keys	1	1	-
Central locking	~		
Remote locking		~	
Sat. Nav. (basic test only)			~
	1		

I have read and understood this condition guide.

Mathew Varghese

Name:

Signature:

10 Aug 2018

Reversing camera