

Report ID: 18,276,263 Version: 1 16 Jul 2018 Created:

Make:	Toyota	Model:	Hiace	Body Style:	People Mover		Pass	Fail	N/A	
Year:	2,013	Registration:		Reg Expiry:		Engine	1		L	
WoF Expiry:	12 Jul 2019	Odometer:	136,389 Kms	Good No:	18276263	Oil level	~			
VIN:	7AT0H60FX18113686	Next Service:	141300	Service Histor		Smoke & fumes	~			
						Performance	~			
	port is not a warranty		f	Danta harra a at		Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
						Coolant condition	~			
						Performance	~			
Key:		-0		-M-		Radiator / Hoses (visual)	~			
S = scratch						Transmission				
						Operation	~			
R = rust PT = paint defe				\prod		Noise	~			
C = crack						Clutch			~	
P = pin dent					741L	CV joints			~	
* = decals	6/16			-NL	ETTPS-	Wheel bearings	~		•	
SC = stone chips						Brakes				
W = significant scuffs						Performance	~			
		Note: som	ne defects & blemishes	may not be disc	blayed in the diagram	Hand Brake	~			
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)				
								mm		
						Right front	3		mm	
						Left rear			mm	
Conditions During Pody Inspection, West						Right rear	3 mm 3 mm			
Conditions During Body Inspection: Wet						Spare	-			
Under Carriage & Under Bonnet Inspection Comments						Suspension	Yes			
	•	·				Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater	•			
						Operation	~			
Interior Comments						Electrical / Accessories				
Seats	Good					Head lights	~			
						Tail lights	~			
Carpets	Good					Indicators	~			
Panels	Good					Dashboard warning lights	~			
						Wipers (front & rear)	~			
Dashboa	rd Good					Window winder FL	~			
						Window winder FR	~			
General C	<u>Comments</u>					Window winder RL	~			
						Window winder RE	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)			~	
						Number of keys	2		-	
Bood Car	Central locking	2								
	ditions During Test	Dive:	Wet			Remote locking	~			
Engine Tir	ming Mechanism:	Cambelt	t			Sat. Nav. (basic test only)			~	
Evidence of Cam Belt Replacement: Yes Kms: 103,307						Reversing camera			~	
Inspected by: Bobby Zhong Date: 16 Jul 2018										

I have read and understood this condition guide.

Name:

Signature: