

Report ID: 18,276,413 Version: 1 Created: 16 Jul 2018

| Make: | Dougoot | Model: | 206 | Body Style: | Hatchhadi | | Pass | Fail | N/A |
|--|--------------------------|------------------|------------------------|-------------------|----------------------|------------------------------|---|-------|----------|
| Year: | Peugeot | Registration: | 206 | Reg Expiry: | Hatchback | Engine | 1 035 | i all | |
| | 2,005 | • | CNF569 | Good No: | 27 Jan 2019 | | | | <u> </u> |
| WoF Expiry: | 03 Aug 2018 | Odometer: | 159,822 Kms | | 18276413 | Oil level | ~ | | <u> </u> |
| VIN: | VF32ANFUR44178052 | Next Service: | ? | Service Histor | y: No | Smoke & fumes | ~ | | |
| Note: This re | port is not a warranty | | | | | Performance | ~ | | <u> </u> |
| This report is | a guide only. Conside | | | | | Noise | ~ | | |
| diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Cooling System | | | |
| | | | | | | Coolant condition | | ~ | <u> </u> |
| Key: | S SC W S | | SW SW | | S D W | Performance | ~ | | |
| S = scratch | | $\overline{(0)}$ | | 5(O)7 | | Radiator / Hoses (visual) | ~ | | |
| D = dent | | | | | A m | Transmission | | | |
| R = rust | s sc w | | | 10 | HI SW | Operation | < | | |
| PT = paint def | ect NP | | | | | Noise | ~ | | |
| C = crack | | | | | S D SC W | Clutch | | | ~ |
| P = pin dent | D SC D B | | | \checkmark | 24116 | CV joints | ~ | | |
| * = decals | | 10 | | 10 | | Wheel bearings | ~ | | 1 |
| SC = stone chips W = significant scuffs | | | | | | Brakes | | | |
| vv = significan | S W S | N V | SW P | | S P W | Performance | ~ | | |
| Dody In | | Note: son | ne defects & blemishes | s may not be disp | layed in the diagram | Hand Brake | ~ | | 1 |
| body inspection comments | | | | | | Tvres (lowest observed tread | Tyres (lowest observed tread depth of tyr | | |
| Dent all over roof. Scratches on inside of windscreen, on right side of screen. Stone chips in windscreen & small stone crack in left side of screen. Cracks in left side plastic sill cover. | | | | | | Left front 6.0 m | | | |
| | | | | | | Right front | | | mm |
| | | | | | | Left rear | 5. | | mm |
| | | | _ | | | Right rear | 3. | - | |
| Conditions During Body Inspection: Dry | | | | | | | 1.8 mm | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Spare Yes | | | |
| Minor oil leak around rocker cover on top of engine & between engine/gearbox area. Rear brake pads | | | | | Suspension | | | | |
| | v. Front brake disc/roto | | 5 5 | | | Suspension performance | ~ | | |
| dirty. | | | | | | Steering performance | ~ | | |
| | | | | | | Shock absorbers | ~ | | |
| | | | | | | Air Conditioning / Heater | | | |
| Interior Comments | | | | | | Operation | | ~ | |
| Interior Comments Good | | | | | | Electrical / Accessories | | | |
| Seats | 0000 | | | | | Head lights | ~ | | |
| Carpets | Good | | | | | Tail lights | ~ | | |
| Carpets | | | | | | Indicators | ~ | | |
| Panels | Good | | | | | Dashboard warning lights | ~ | | |
| Deall | Good | | | | | Wipers (front & rear) | ~ | | |
| Dashboa | ra | | | | | Window winder FL | ~ | | |
| | | | | | | Window winder FR | ~ | | |
| General Comments | | | | | Window winder RL | ~ | | | |
| Key remote not working to lock & unlock vehicle, one of rubber button missing out of key. AC not very cold, needs attention. | | | | | Window winder RR | ~ | | 1 | |
| neeus allef | | | | | | Rear view mirrors | ~ | | 1 |
| | | | | | | Radio (basic test only) | ~ | | 1 |
| | | | | | | CD (basic test only) | ~ | | 1 |
| | | | | | | Number of keys | 2 | | 1 |
| Road Car | ditions During Test | Drivo | | | | Central locking | 2 V | | |
| nuau CON | uning resi | Dive. | Dry | | | Remote locking | | ~ | |
| Engine Ti | ning Mechanism: | Cambel | t | | | Sat. Nav. (basic test only) | | * | V |
| - | of Cam Belt Replac | | 'es | Kms: 12 | 1,666 | Reversing camera | | | v v |
| | | | | 12 | | | | | |
| Inspecte | d by: Jason Young | | | | | Date: 13 Jul 201 | 8 | | |
| | | | | | | | | | |
| I have read | and understood th | is condition g | juide. Name: | | | Signature: | | | |