

Report ID: 18,276,445 Version: 1 Created: 27 Jul 2018

Make:	Hyundai	Model:	Tucson	Body Style:	SUV		Pass	Fail	N/A
Year:	2,010	Registration:	FLY155	Reg Expiry:	30 Jul 2018	Engine	1	1	
WoF Expiry:	03 Aug 2019	Odometer:	63,509 Kms	Good No:	18276445	Oil level	~		
VIN:	KMHJN81BMAU18379	Next Service:	73,000	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	r		
	port is not a warranty	aration is made	for ago and milaago	Parts have not	been dismontled or	Noise	V		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechar	ical inspection prior to	purchase and tl	his can be arranged fo	r an additional o	charge.	Coolant condition	~		
						Performance	~		
Key:	S	-0	S SC S SC	-161-	S SC	Radiator / Hoses (visual)	v		
S = scratch						Transmission			
D = dent	s sc			The	S SC	Operation	~		
R = rust PT = paint def				\prod		Noise	~		
C = crack						Clutch			~
P = pin dent						CV joints	~		
* = decals	s sc PIK			AL.	ELTR SC	Wheel bearings	~		
SC = stone chips						Brakes	V		
W = significant scuffs W S SC S S SC						Performance	~		
Note: come defecte % blamiches may not be displayed in the diagram						Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram								ofture	
						Tyres (lowest observed tread depth of tyres) Left front 7.7 mn			
						Left front		, .,	
						Right front		.4	mm
						Left rear		.4	mm
Conditions During Body Inspection: Dry						Right rear	3.8 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
	inage & onder bor	mermspectic	<u>on comments</u>			Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation	~		
Good						Electrical / Accessories	1		
Seats	0000					Head lights	~		
Carpets	Good					Tail lights	~		
	Cood					Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	Good					Wipers (front & rear)	~		
Dashboa						Window winder FL	~		
						Window winder FR	~		
General (<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Con	ditions During Test	t Drive:	Dry			Central locking	~		
	-					Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: Y	′es	Kms: 14	10,000	Reversing camera			~
Inspected by: Ian Dunn Date: 18 Jul 2018									
I have read and understood this condition guide. Name:									