

Report ID: 18,278,229 Version: 1 16 Jul 2018 Created:

Make:	Mazda	Model:	CX-7	Body Style:	Wagon	1Г		Pass	Fail	N/A	
Year:	2,008	Registration:		Reg Expiry:	<b>.</b> -	╞	ingine			I	
WoF Expiry:		Odometer:	96,375 Kms	Good No:	18278229		Oil level	~			
VIN:	7AT0C13PX18106279	Next Service:		Service Histor			Smoke & fumes	~			
						it	Performance	· ·			
	port is not a warranty		for any and miles as	Danta hava nat	hoon disconting of	lŀ	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System					
						IF	Coolant condition	~		[	
						iŀ	Performance	~			
Key:		-0					Radiator / Hoses (visual)	~			
S = scratch	STE	A CO			The	╞	ransmission	•			
D = dent	GIE			1n-		Iŀ	Operation	~			
R = rust				10			Noise	~			
PT = paint def C = crack	ect					Iŀ	Clutch	•		~	
P = pin dent	Ho				JUII —	1	CV joints	~			
* = decals	- MIK			AL-	ENR	۱ŀ	Wheel bearings	v v			
SC = stone chips						╢┝	Brakes				
W = significant scuffs							Performance				
		Noto: com	dofocts & blomishos		laved in the diagram			-			
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							Hand Brake	<ul> <li></li> </ul>			
						Tyres (lowest observed tread depth of tyres)					
							Left front	2		mm	
							Right front	2		mm	
						╣┝	Left rear	2		mm	
Conditions During Body Inspection: Dry							Right rear 3			mm	
						٦Ļ	Spare Yes				
Under Carriage & Under Bonnet Inspection Comments						S	Suspension				
							Suspension performance	~			
							Steering performance	~			
							Shock absorbers	~			
						A	Air Conditioning / Heater				
						٦L	Operation	~			
Interior Comments						E	Electrical / Accessories				
Seats	Good						Head lights	~			
Carpote	Good						Tail lights	~			
Carpets							Indicators	~			
Panels	Good					[	Dashboard warning lights	~			
	Good						Wipers (front & rear)	~			
Dashboa	ira						Window winder FL	~			
						╣Ӷ	Window winder FR	~			
General Comments							Window winder RL	~			
							Window winder RR	~			
							Rear view mirrors	~			
							Radio (basic test only)	~			
							CD (basic test only)	~			
						┘┞	Number of keys	1			
Road Conditions During Test Drive: Dry						٦٢	Central locking	~			
						╎┝	Remote locking	~			
Engine Timing Mechanism: Timing Chain							Sat. Nav. (basic test only)			~	
Evidence of Cam Belt Replacement: Not Applicable Kms:							Reversing camera	~		·	
L						J L	<u> </u>	-			
Inspected by: Bobby Zhong Date: 16 Jul 2018											

I have read and understood this condition guide.

Name: .....

Signature: .....