

Report ID: 18,278,361 Version: 1 Created: 02 Aug 2018

Make:	Suzuki	Model:	Splash	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2,009	Registration:	-	Reg Expiry:		Engine	1		L
WoF Expiry:	,	Odometer:	67,473 Kms	Good No:	18278361	Oil level	~		
VIN:	TSMEXB32S00209609	Next Service:	77460	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for ago and milaago	Darts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	r an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:	S	-0	S			Radiator / Hoses (visual)	~		
S = scratch	RE	A U			Ton los	Transmission			
D = dent	s sc			The		Operation	~		
R = rust PT = paint defe				\prod	JUIL	Noise	~		
C = crack				$+ \mathbf{\nabla}$	P	Clutch			~
P = pin dent						CV joints	~		-
* = decals	sc 916			-NL	ETPS-	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs						Performance	~		
		Note: som	ne defects & blemishes	may not be disc	laved in the diagram	Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Tyres (lowest observed tread		oftvre	<u> </u>
						Left front 8 mm			
						Right front			 mm
						Left rear	3		mm
Conditions During Body Inspection: Dry						Right rear	8 mm		111111
Under Carriage & Under Bonnet Inspection Comments						Suspension	Spare Yes		
						•			1
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
Good						Electrical / Accessories			T
Seats						Head lights	~		
Carpets	Good					Tail lights	~		
	Good					Indicators	~		
Panels						Dashboard warning lights	~		<u> </u>
Dashboa	rd Good					Wipers (front & rear)	~		<u> </u>
	-					Window winder FL	~		<u> </u>
Conorol	Comments					Window winder FR	~		<u> </u>
						Window winder RL	~		<u> </u>
						Window winder RR	~		<u> </u>
						Rear view mirrors	~		<u> </u>
						Radio (basic test only)	~		<u> </u>
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
Engine Timing Mechanism: Timing Chain						Remote locking	~		<u> </u>
						Sat. Nav. (basic test only)			~
Evidence	or Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: John Lindsay Date: 02 Aug 2018									
Date. 02 Aug 2010									

I have read and understood this condition guide.

Name:

Signature: