

Report ID: 18,278,650 Version: 5 08 Aug 2018 Created:

Make:	BMW	Model:	3 Series	Body Style:	Sedan		Pass	Fail	N/A
Year:	2,008	Registration:	JDY216	Reg Expiry:	02 Jul 2018	Engine		1	•
WoF Expiry:	25 Jul 2019	Odometer:	92,434 Kms	Good No:	18278650	Oil level	~		
VIN:	WBAVH16060NK9272	Next Service:	96,020	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a guide only. Conside	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	r an additional c	harge.	Coolant condition	~		
					S	Performance	~		
Key:		-0	S S	$\neg \bigcirc \square$		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
R=rust SW AA						Operation	~		
PT = paint defect						Noise	~		
C = crack						Clutch			~
P = pin dent						CV joints			~
						Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
W - significant scurs W S						Performance	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		
RH wing mirror not working						Tyres (lowest observed tread depth of tyres)			
Audio knob missing						Left front 6		5	mm
Ignition key cover need attention, remote not working						Right front	6 mm		mm
						Left rear	e	5	mm
Conditions During Body Inspection: Dry						Right rear 6		mm	
						Spare N/A			
Under Carriage & Under Bonnet Inspection Comments					Suspension				
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
Carpets	Average					Tail lights	~		
						Indicators	~		
Panels	Average					Dashboard warning lights		~	
Dashboa	rd Good					Wipers (front & rear)	~		
						Window winder FL	~		
Canada						Window winder FR	~		
General Comments Tyre pressure light on						Window winder RL	~		
i yre pressu						Window winder RR	~		
						Rear view mirrors		~	
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
Engine Ti	ning Mechanism:	Timine	Chain			Remote locking		~	
						Sat. Nav. (basic test only)			~
	or carri bert nepiac		lot Applicable	11113.		Reversing camera			~
Inspected by: Mathew Varghese Date: 08 Aug 2018									

I have read and understood this condition guide.

Name:

Signature: