

Report ID: 18,278,728 Version: 1 Created: 01 Aug 2018

Make:	Toyota	Model:	Ractis	Body Style: Hatchback		Pass	Fail	N/A	
Year:	2,010	Registration:	nacus	Reg Expiry:	Engine				
WoF Expiry:		Odometer:	75,233 Kms	Good No: 18278728	Oil level	~			
VIN:	7AT0H652X18004351	Next Service:		Service History: No	Smoke & fumes	~			
	7810H052818004551		03229	NO	Performance	~			
	port is not a warranty				Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends									
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.					Cooling System Coolant condition				
					Performance	~			
Key:		-0	S		Radiator / Hoses (visual)	ン ン		-	
S = scratch	ST	0			Transmission	V			
D = dent								T	
R = rust					Operation Noise	~		-	
PT = paint def C = crack	ect M				Clutch	~			
P = pin dent	LHC	KI						~	
* = decals	MIR				CV joints	~			
SC = stone chips					Wheel bearings	Wheel bearings			
W = significant scuffs								<u> </u>	
		Nata			Performance	~			
Body Insp	pection Comments	Note: som	ie delects & blemisnes	may not be displayed in the diagram	Hand Brake	~	<u>.</u>	Ļ	
					Tyres (lowest observed tread depth of tyres)				
					Left front	5		mm	
					Right front	5		mm	
					Left rear	5 mm			
Conditions During Body Inspection: Dry					Right rear	5 mm			
Under Carriage & Under Bonnet Inspection Comments					Spare Yes				
	inage & onder boi	metmspectic	<u>In comments</u>		Suspension				
					Suspension performance	~			
					Steering performance	~			
		Shock absorbers	~						
					Air Conditioning / Heater			1	
Interior Comments					Operation 🖌				
stains rear seats					Electrical / Accessories			T	
Seats	stants real	scats			Head lights	~		<u> </u>	
Carpets	Good				Tail lights	~			
	Cood				Indicators	~			
Panels	Good				Dashboard warning lights	~		<u> </u>	
Dashboa	rd Good				Wipers (front & rear)	~		<u> </u>	
					Window winder FL	~		<u> </u>	
Consul	ommorte				Window winder FR	~		<u> </u>	
<u>General Comments</u>					Window winder RL	~		<u> </u>	
					Window winder RR	~		<u> </u>	
					Rear view mirrors	~			
					Radio (basic test only)	~			
		CD (basic test only)	~						
					Number of keys	1			
Road Conditions During Test Drive: Dry						~			
Engine T	ming Mechanism:	Timing			Remote locking	~			
-	Sat. Nav. (basic test only)			~					
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:	Reversing camera			~	
Inspected by: John Lindsay Date: 01 Aug 2018									

I have read and understood this condition guide.

Name:

Signature: