

Report ID: 18,278,825

Version: 2

Engine

Oil level

Created: 29 Jul 2018

Pass


N/A

Fail

Make: Model: **Body Style:** Sedan Honda Accord Year: Registration: **Reg Expiry:** 2,011 **GLY297** 01 Aug 2018 WoF Expiry: **Odometer: Good No:** 18278825 02 May 2019 148,674 Kms VIN: **Next Service: Service History:** MRHCP3650BP040103 146412 Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>				
Seats	Average			
Carpets	Average			
Panels	Average			
Dashboard	Average			

General Comments

Inspected by:

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Cambelt

Xinghui Lin

Evidence of Cam Belt Replacement:

Kms: Yes 111,911

Smoke & fumes 1 Performance V Noise / Cooling System Coolant condition Performance Radiator / Hoses (visual) **Transmission** Operation V Noise 1 Clutch 1 CV joints Wheel bearings Brakes Performance **Hand Brake** Tyres (lowest observed tread depth of tyres) Left front mm Right front mm 3.5 Left rear 4.5 mm Right rear mm 4 Spare Yes Suspension Suspension performance Steering performance 1 Shock absorbers Air Conditioning / Heater Operation **Electrical / Accessories** Head lights Tail lights Indicators Dashboard warning lights / Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors / Radio (basic test only) 1 CD (basic test only) 1 Number of keys 3 Central locking Remote locking Sat. Nav. (basic test only) ~ Reversing camera 1

I have read and understood this condition guide.

Name			

29 Jul 2018

Date: