

Report ID: 18,278,856 Version: 3 12 Mar 2019 Created:

Make:	Mazda	Model:	Mazda6	Body Style:	Sedan		Pass	Fail	N/A
Year:	2008	Registration:	EQS158	Reg Expiry:	17 Jul 2019	Engine			
WoF Expiry:	26 Jun 2019	Odometer:	112,972 Kms	Good No:	18278856	Oil level	~		
VIN:	JM0GH105100116725	Next Service:	115,000kms	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	or an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:	SC W	-0	S SC S P		s	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	S D PT			215	SW	Operation	~		
R = rust PT = paint defe				$\left(\left \right\rangle \right)$		Noise	~		
C = crack				+	SC	Clutch			~
P = pin dent					게비	CV joints	~		
* = decals	ssc 916			- No	ETTY S	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs SC S S D P S P S S S P						Performance	~		
		Note: som	ne defects & blemishes	s may not be disc	laved in the diagram	Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Tyres (lowest observed tread	•	oftvre	
Electric wing mirrors fail. Stonechips on windscreen. Boot button damage/fail . Spare wheel well has moisture and surface rust.									mm
Scratches on LH sill. Paint coming off front bumper RHS.						Right front			mm
						Left rear		3	mm
								5	-
Conditions During Body Inspection: Wet						Right rear	4 mm		
Under Carriage & Under Bonnet Inspection Comments						Suspension	Spare Yes		
Average co	-					-			
/werage co						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			1
Interior Comments						Operation 🖌			
Average						Electrical / Accessories			
Seats	/ Telege					Head lights	~		
Carpets	Average					Tail lights	~		
	Average					Indicators	~		
Panels	Average					Dashboard warning lights	~		<u> </u>
Dashboa	rd Average					Wipers (front & rear)	~		<u> </u>
						Window winder FL	~		<u> </u>
Concert						Window winder FR	~		ļ
Drives well.	<u>Comments</u>					Window winder RL	~		<u> </u>
Drives well.						Window winder RR	~		ļ
						Rear view mirrors		~	
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1	1	
Road Conditions During Test Drive: Wet						Central locking	~		
с		T ''				Remote locking	~		
-	ming Mechanism:	Timing (Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Roger King Date: 12 Mar 2010									
Inspected by: Roger King Date: 12 Mar 2019									

I have read and understood this condition guide.

Name:

Signature: