

Basic Vehicle Condition Guide

Reg Expiry:

Report ID: 18,278,904

Version: 1

Created: 30 Jul 2018

Make: Toyota Model: Blade Body Style: Hatchback

 WoF Expiry:
 22 Jun 2019
 Odometer:
 79,806 Kms
 Good No:
 18278904

 VIN:
 7AT0H656X18012189
 Next Service:
 89,800
 Service History:
 No


Registration:

Note: This report is not a warranty

2,007

Year:

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

| <u>Interior Comments</u> | | | | |
|--------------------------|------|--|--|--|
| Seats | Good | | | |
| Carpets | Good | | | |
| Panels | Good | | | |
| Dashboard | Good | | | |

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: lan Dunn Date: 30 Jul 2018

Name:

| | _ | | | |
|--|-----------------------|------|---------------------------------------|--|
| | Pass | Fail | N/A | |
| Engine | | | | |
| Oil level | • | | | |
| Smoke & fumes | v v | | | |
| Performance | • | | | |
| Noise | ' | | | |
| Cooling System | | | | |
| Coolant condition | ' | | | |
| Performance | • | | | |
| Radiator / Hoses (visual) | • | | | |
| Transmission | | | | |
| Operation | V | | | |
| Noise | - | | | |
| Clutch | | | ~ | |
| CV joints | • | | | |
| Wheel bearings | ' | | | |
| Brakes | | | | |
| Performance | - | | | |
| Hand Brake | <i>'</i> | | <u> </u> | |
| Tyres (lowest observed tread depth of tyres) | | | | |
| Left front | 7.5 | | mm | |
| Right front | | .9 | mm | |
| Left rear | 7.7 | | mm | |
| Right rear | 7.3 mm | | mm | |
| Spare | | Yes | | |
| Suspension | | | 1 | |
| Suspension performance | V | | | |
| Steering performance | • | | | |
| SHOCK absorbers | | | | |
| Air Conditioning / Heater | | | | |
| Operation 🗸 | | | | |
| Electrical / Accessories | | | | |
| Head lights | • | | | |
| Tail lights Indicators | | | | |
| | | | | |
| Dashboard warning lights | | | | |
| Wipers (front & rear) Window winder FL | | | | |
| Window winder FR | | | | |
| Window winder RL | V V V V V | | | |
| Window winder RR | • | | | |
| Rear view mirrors | V | | | |
| | | ., | | |
| Radio (basic test only) | | • | | |
| CD (basic test only) Number of keys | 2 | | | |
| · | 2 | | | |
| Central locking | • | | | |
| Remote locking | | | | |
| Sat. Nav. (basic test only) | | | \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ | |
| Reversing camera | | | | |

Signature: