

## **Basic Vehicle Condition Guide**

Report ID: 18,278,943

Version:


Created: 04 Aug 2018

Make: Model: Mazda Demio **Body Style:** Hatchback

Year: 2,009 Registration: Reg Expiry: **WoF Expiry: Odometer: Good No:** 19 Jun 2019 18278943 83,198 Kms VIN: 7AT0C12HX18183754 **Next Service: Service History:** 93,188

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



**Body Inspection Comments** 

Radio needs band expander

**Conditions During Body Inspection:** Dry

**Under Carriage & Under Bonnet Inspection Comments** 

Interior Comments				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

	_
General	Comments

Road Conditions During Test Drive: Dry

**Engine Timing Mechanism: Timing Chain** 

**Evidence of Cam Belt Replacement:** Kms: Not Applicable

01 Aug 2018 Inspected by: lan Dunn Date:

Name: .....

	Pass	Fail	N/A		
Engine					
Oil level	~				
Smoke & fumes	~				
Performance	\( \times \)				
Noise	~				
Cooling System					
Coolant condition	~				
Performance	<b>v</b>				
Radiator / Hoses (visual)	~				
Transmission					
Operation	~				
Noise	~				
Clutch			~		
CV joints	~				
Wheel bearings	~				
Brakes					
Performance	~				
Hand Brake	~				
Tyres (lowest observed tread	d depth	of tyre	es)		
Left front	6.7		mm		
Right front	7.1		mm		
Left rear	7.1		mm		
Right rear	6.4		mm		
Spare	Yes				
Suspension					
Suspension performance	~				
Steering performance	<i>V</i>				
Shock absorbers	~				
Air Conditioning / Heater					
Operation	~				
Electrical / Accessories					
Head lights	~				
Tail lights	~				
Indicators	~				
Dashboard warning lights	V V V V				
Wipers (front & rear)	~				
Window winder FL	~				
Window winder FR	~				
Window winder RL	~				
Window winder RR	~				
Rear view mirrors	~				
Radio (basic test only)		~			
CD (basic test only)	~				
Number of keys	2	<u> </u>	1		
Central locking	~				
Remote locking	~				
Sat. Nav. (basic test only)			~		
Reversing camera			~		
i -	1	1	1		

Signature: .....