

## **Basic Vehicle Condition Guide**

Report ID: 18,279,564


Version: 1

Created: 20 Aug 2018

Make: Model: Corolla **Body Style:** Toyota Wagon Year: Registration: **Reg Expiry:** 2,007 WoF Expiry: **Odometer: Good No:** 09 Jul 2019 49,248 Kms 18279564 VIN: **Next Service: Service History:** 7AT0H607X18026139 59238

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Wet

**Under Carriage & Under Bonnet Inspection Comments** 

<u>Interior Comments</u>	
Seats	Good
Carpets	Good
Panels	Good
Dashboard	Good

**General Comments** 

Inspected by:

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Fail N/A Pass Engine Oil level Smoke & fumes 1 Performance V Noise / Cooling System Coolant condition Performance Radiator / Hoses (visual) **Transmission** Operation V Noise 1 Clutch 1 CV joints Wheel bearings Brakes Performance **Hand Brake** Tyres (lowest observed tread depth of tyres) Left front mm Right front 7 mm Left rear 7 mm Right rear  $\mathsf{mm}$ 7 Spare Yes Suspension Suspension performance Steering performance 1 Shock absorbers Air Conditioning / Heater Operation **Electrical / Accessories** Head lights Tail lights Indicators Dashboard warning lights / Wipers (front & rear) / Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors / Radio (basic test only) 1 CD (basic test only) 1 Number of keys 1 Central locking Remote locking

I have read and understood this condition guide.

John Lindsay

Name: .....

Signature: .....

20 Aug 2018

1

1

Sat. Nav. (basic test only)

Date:

Reversing camera