

Report ID: 18,279,852 Version: 2 18 Aug 2018 Created:

| Make: | Honda | Model: | Stream | Body Style: | SUV | | Pass | Fail | N/A |
|--|------------------------|---------------|------------------------|-----------------|----------------------|--|--------|------|-----|
| Year: | 2,005 | Registration: | Sacam | Reg Expiry: | 50 v | Engine | | | |
| WoF Expiry: | 2,005 26 Jun 2019 | Odometer: | 62,095 Kms | Good No: | 18279852 | Oil level | ~ | | |
| VIN: | 7AT08GADX18015932 | | | Service Histor | | Smoke & fumes | ~ | | |
| | 74100040710013932 | | 72,100 | | · 110 | Performance | v v | | |
| | port is not a warranty | | | | | Noise | ~ | | |
| | a guide only. Conside | | | | | | V | | |
| diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Cooling System | | | |
| | | | | | | Coolant condition | ~ | | |
| Key: | | | S SC S SC | | S | Performance | ~ | | |
| S = scratch | R | (0) | <u>À</u> | 105 | ~ | Radiator / Hoses (visual) | ~ | | |
| D = dent | | | | | Elh sc | Transmission | | 1 | |
| R = rust | MID | | | | HUK | Operation | ~ | | |
| PT = paint def | ect N | | | | | Noise | ~ | | |
| C = crack | | | | | | Clutch | | | ~ |
| P = pin dent * = decals | sc dl | | | | 1845 | CV joints | ~ | | |
| SC = stone chi | | 10 | | 70 | | Wheel bearings | ~ | | |
| W = significant scuffs | | | | | | Brakes | | | |
| | W | | | | | Performance | ~ | | |
| Body Insi | pection Comments | Note: son | ne defects & blemishes | may not be disp | layed in the diagram | Hand Brake | ~ | | |
| Radio needs band expander | | | | | | Tyres (lowest observed tread depth of tyres) | | | |
| | | | | | | Left front 6.8 n | | | mm |
| | | | | | | Right front | 6 | .8 | mm |
| | | | | | | Left rear | 6 | .9 | mm |
| Conditions During Body Inspection: Dry | | | | | | Right rear | 7.2 mm | | mm |
| | | | | | | Spare | Yes | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Suspension | | | |
| | | | | | | Suspension performance | ~ | | |
| | | | | | | Steering performance | ~ | | |
| | | | | | | Shock absorbers | ~ | | |
| | | | | | | Air Conditioning / Heater | | | |
| | | | | | | Operation | ~ | | |
| Interior Comments | | | | | | Electrical / Accessories | | | |
| Seats | Good | | | | | Head lights | ~ | | |
| | | | | | | Tail lights | ~ | | |
| Carpets | Good | | | | | | - | | |
| | Good | | | | | Indicators | ~ | | |
| Panels | | | | | | Dashboard warning lights | ~ | | |
| Dashboa | rd Good | | | | | Wipers (front & rear) | ~ | | |
| | | | | | | Window winder FL | ~ | | |
| General | <u>Comments</u> | | | | | Window winder FR | ~ | | |
| | | | | | | Window winder RL | ~ | | |
| | | | | | | Window winder RR | ~ | | |
| | | | | | | Rear view mirrors | ~ | | |
| | | | | | | Radio (basic test only) | | ~ | |
| | | | | | | CD (basic test only) | ~ | | |
| | | | | | | Number of keys | 2 | | |
| Road Conditions During Test Drive: Dry Central locking | | | | | | | ~ | | |
| | - | | | | | Remote locking | ~ | | |
| Engine Timing Mechanism: Cambelt Sat. Nav. (basic test only) | | | | | | | | | ~ |
| Evidence | of Cam Belt Replac | ement: N | lo | Kms: | | Reversing camera | ~ | | |
| | | | | | | | | I | |
| Inspected by: Brad Lucas Date: 18 Aug 2018 | | | | | | | | | |
| | | | | | | | | | |

I have read and understood this condition guide.

Name:

Signature: