

Basic Vehicle Condition Guide

Report ID: 18,280,535

Version:

Engine

Oil level

Noise

Smoke & fumes

Performance

Cooling System

Transmission

Operation

Noise

Clutch

Brakes

CV joints

Wheel bearings

Performance

Hand Brake

Left front

Right front

Left rear

Right rear

Suspension

Shock absorbers Air Conditioning / Heater

Electrical / Accessories

Dashboard warning lights

Wipers (front & rear) Window winder FL Window winder FR

Window winder RL Window winder RR Rear view mirrors

Radio (basic test only)

CD (basic test only)

Number of keye

Operation

Head lights Tail lights Indicators

Suspension performance Steering performance

Spare

Coolant condition Performance

Radiator / Hoses (visual)

Created: 23 Jul 2018

Pass

1

~

/

V

1

Tyres (lowest observed tread depth of tyres)

N/A

1

mm

mm

mm

 mm

4

5

3

1

/

1

1

V


Yes

Fail

Make: Model: Ford **Body Style:** Hatchback Mondeo Year: Registration: GKW870 **Reg Expiry:** 2,012 27 Sep 2018 **Odometer:** WoF Expiry: 28 Sep 2018 **Good No:** 18280535 162,590 Kms VIN: WF0EXXGBBECR59702 **Next Service: Service History:** 182,000 No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Ignition key getting stuck while removing

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Interior Comments				
Seats	Average			
Carpets	Average			
Panels	Average			
Dashboard	Good			

General Comments

I have

Road

Engi Evid

	I Nullibel of keys	1 1	
oad Conditions During Test Drive: Dry	Central locking	~	
-	Remote locking	~	
gine Timing Mechanism: Cambelt	Sat. Nav. (basic test onl	y)	~
ridence of Cam Belt Replacement: No Kms:	Reversing camera		V
Inspected by: Mathew Varghese	Date: 23 Jul	2018	
ve read and understood this condition guide. Name:	Signature: .		