

Report ID: 18,280,808 Version: 1 18 Jul 2018 Created:

Make:	Toyota	Model:	Corolla	Body Style:	Sedan		Pass	Fail	N/A
Year:	2,014	Registration:	HRL789	Reg Expiry:	02 Oct 2018	Engine			
WoF Expiry:	04 Oct 2018	Odometer:	108,288 Kms	Good No:	18280808	Oil level	~		
VIN:	MR053REH205262408	Next Service:	110000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for any and milages	Darts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends									
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	~		
		_				Performance	~		
Key:	PT SC W	-0	S PT SC	-161-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	S PT C SC			The	S PT	Operation	~		
R = rust PT = paint defe				\prod	JHIH	Noise	~		
C = crack					SC	Clutch	•		~
P = pin dent						CV joints	~		•
* = decals	RSC 916			The	ETTPS-	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs PT W D PT SC W D						Performance	~		
		Noto: com				Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram								oftyre))
Grill broken Right side wing mirror housing broken						Tyres (lowest observed tread depth of tyres) Left front 6 mm			
Right side wing minor housing bloken						Right front	6		mm
						Left rear	3		-
							8		mm
Conditions During Body Inspection: Dry						Right rear	6 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes Suspension			
						Suspension performance	V		
						Steering performance	~		
						Shock absorbers	-		
		~							
						Air Conditioning / Heater			
Interior Comments						Operation			
Stains on seats						Electrical / Accessories			
Seats						Head lights	~		
Carpets	Hole in dri	vers carpet				Tail lights	~		
	Average					Indicators	~		
Panels						Dashboard warning lights	~		
Dashboa	rd Average					Wipers (front & rear)	~		
						Window winder FL	~		
General (Comments					Window winder FR	~		
	<u>commento</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	3		
Road Conditions During Test Drive: Dry						Central locking	~		
Engine Timing Mechanism: Timing Chain Remote locking							~		
						Sat. Nav. (basic test only)			~
Evidence	ог сант вен керіас	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: John Lindsay Date: 18 Jul 2018									

I have read and understood this condition guide.

Name:

Signature: