

Basic Vehicle Condition Guide

Report ID: 18,281,042

Version: 2

Engine

Created: 17 Jul 2018

Pass


Fail

N/A

Make: Model: Skoda Fabia **Body Style:** Hatchback Year: 2,016 Registration: JPF26 Reg Expiry: 20 Jan 2019 Good No: WoF Expiry: **Odometer:** 21 Jan 2019 18281042 27,846 Kms VIN: TMBFM6NJ5GZ03676 **Next Service: Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Test

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Good condition.

Interior Comments				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

General Comments

Inspected by:

Drives ok.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Roger King

Evidence of Cam Belt Replacement: No

Kms:

Oil level	🗸		
Smoke & fumes	~		
Performance	v v		
Noise	~		
Cooling System	•		
Coolant condition	~		
Performance	\(\triangle \)		
Radiator / Hoses (visual)	~		
Transmission			
Operation	V		
Noise	~		
Clutch	~		
CV joints	\(\times \)		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	d depth	of tyre	es)
Left front		4	mm
Right front	4		mm
Left rear	4		mm
Right rear	5		mm
Spare	Yes		
Suspension			
Suspension performance	~		
Steering performance	\(\times \)		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)			~
Number of keys	2		
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			1

I have read and understood this condition guide.

Name [.]			

17 Jul 2018

1

Reversing camera