

Report ID: 18,281,618 Version: 1 27 Jul 2018 Created:

Make:	Mazda	Model:	Axela	Body Style:	Hatchback		Pass	Fail	N/A	
Year:	2,004	Registration:	GNZ224	Reg Expiry:	04 Oct 2018	Engine	-1	1		
WoF Expiry:	05 Jul 2019	Odometer:	178,713 Kms	Good No:	18281618	Oil level	~			
VIN:	7AT0C13JX12113076	Next Service:	Just serviced	Service Histor	y: No	Smoke & fumes	~			
						Performance	~			
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechar	ical inspection prior to	purchase and t	nis can be arranged fo	or an additional o	harge.	Coolant condition	~			
						Performance	~			
Key:	S	-0		-01-		Radiator / Hoses (visual)	~			
S = scratch						Transmission	Transmission			
D = dent	- HE			TIS	SW	Operation	~			
R = rust PT = paint def				\prod		Noise	~			
C = crack						Clutch			~	
P = pin dent	HIG				세비	CV joints	~			
* = decals	- Ole			- Jul	HIP	Wheel bearings	~			
SC = stone chips						Brakes				
W = significant scuffs W W W						Performance	~			
D = -l. L		Note: son	ne defects & blemishes	may not be disc	layed in the diagram	Hand Brake	~			
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			es)	
						Left front 3.0 mm				
						Right front		.0	mm	
						Left rear	+	.0	mm	
Conditions During Rody Inspections						Right rear	-	.0	mm	
Conditions During Body Inspection: Dry						Spare Yes				
Under Carriage & Under Bonnet Inspection Comments						Suspension				
	-					Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater	•			
						Operation				
Interior Comments						Electrical / Accessories	•			
Seats Average						Head lights	~			
						Tail lights	~			
Carpets	Average					Indicators	~			
Panels	Average					Dashboard warning lights				
	<u> </u>					Wipers (front & rear)	~			
Dashboa	ard Average					Window winder FL	~			
	I					Window winder FR	~			
General Comments						Window winder RL	~			
						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	1	1	1	
Road Conditions During Test Drive: Dry						Central locking	· ·			
Road Conditions During Test Drive: Dry						Remote locking	~			
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~	
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~	
	•	•	- 1-1				1		-	
Inspected by: Dion Mair Date: 17 Jul 2018										

I have read and understood this condition guide.

Name:

Signature: