

Report ID: 18,281,911 Version: 1 24 Jul 2018 Created:

Make:	Mazda	Model:	Mazda6	Body Style:	Wagon][Pass	Fail	N/A	
Year:	2,004	Registration:	BSS182	Reg Expiry:	11 Aug 2018		Engine				
WoF Expiry:	10 Jul 2019	Odometer:	252,498 Kms	Good No:	18281911	ļļ	Oil level	~			
VIN:	JM0GY103100102008	Next Service:	due	Service Histor	y: Yes	١t	Smoke & fumes	~			
						īľ	Performance	~			
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or							Noise	~			
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends							Cooling System				
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.							Coolant condition	~			
						٦ŀ	Performance	~			
Key: SSCW SW						IF	Radiator / Hoses (visual)	~			
S = scratch						lŀ	Transmission			1	
D = dent R = rust SSC W						l	Operation	~			
PT = paint defect							Noise	~			
C = crack							Clutch			~	
P = pin dent							CV joints	~			
* = decals SDSCW 919 SW							Wheel bearings	~			
SC = stone chips							Brakes	-			
W = significant scuffs SC S W S SC W S SC W						lŀ	Performance	~			
						Iŀ	Hand Brake	~			
Body Inspection Comments						1ŀ	Tyres (lowest observed tread	l depth	of tyre	es)	
Bonet pull broken						Iŀ	Left front 0.0 mm				
						lŀ	Right front 0.0			mm	
						Jŀ	Left rear	2.0		mm	
Conditions During Body Inspection: Dry						٦ŀ	Right rear	2.0		mm	
Conditions During Body Inspection: Dry						<u></u>	Spare Yes				
Under Carriage & Under Bonnet Inspection Comments							Suspension				
Front two tyers iner edge worn						lŀ	Suspension performance	~			
						lŀ	Steering performance	•	~		
Oil leak at engine							Shock absorbers	~	•		
							Air Conditioning / Heater	•			
						ļŀ	Operation				
Interior Comments							Electrical / Accessories				
Seats Average						lŀ	Head lights	~			
						lŀ	Tail lights	~			
Carpets	Average					lŀ	Indicators	~			
Panels	Good					H	Dashboard warning lights	~			
							Wipers (front & rear)	~			
Dashboa	rd Good						Window winder FL	~			
						<u></u> ↓	Window winder FR	~			
General Comments							Window winder RL	~			
Noise from steering							Window winder RR	~			
						H	Rear view mirrors	· ·			
						Iŀ	Radio (basic test only)	~			
						╢	CD (basic test only)	• •			
] ŀ	Number of keys	1	I		
Road Conditions During Test Driver						┓┠	Central locking				
Road Conditions During Test Drive: Dry						」 ┠	Remote locking	~			
Engine Timing Mechanism: Timing Chain]	Sat. Nav. (basic test only)	-		~	
Evidence of Cam Belt Replacement: Not Applicable Kms:							Reversing camera			~	
Inspected by: Dion Mair Date: 23 Jul 2018											

I have read and understood this condition guide.

Name:

Signature: