

Report ID: 18,282,154 Version: 1 Created: 19 Jul 2018

| Make: | Peugeot | Model: | 308 | Body Style: | Hatchback | | Pass | Fail | N/A | |
|--|--|----------------------|------------------------|---------------------|----------------------|---|------|--------|--------|--|
| Year: | 2,009 | Registration: | EYS53 | Reg Expiry: | 29 Oct 2018 | Engine | 1 | I | | |
| WoF Expiry: | 18 Nov 2018 | Odometer: | 156,815 Kms | Good No: | 18282154 | Oil level | ~ | | | |
| VIN: | VF34C9HZH55187066 | Next Service: | 160927 | Service Histor | y: No | Smoke & fumes | ~ | | | |
| | | | | | | Performance | ~ | | | |
| | port is not a warranty | aration is made | for age and mileage | Parts have not | been dismantled or | Noise | ~ | | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Cooling System | | | | |
| a full mechan | ical inspection prior to | purchase and th | nis can be arranged fo | r an additional o | harge. | Coolant condition | ~ | | | |
| | | | | | | Performance | ~ | | | |
| Key: | S SC | -0 | S P SC S P SC | -01- | s | Radiator / Hoses (visual) | ~ | | | |
| S = scratch | | | | | | Transmission | | | | |
| D = dent | s sc | | | The | HIL S | Operation | ~ | | | |
| R = rust PT = paint defe | | | | \prod | 1711A | Noise | ~ | | | |
| C = crack | | | | $+ \mathbf{\nabla}$ | | Clutch | | | ~ | |
| P = pin dent | | | | | 세비 | CV joints | ~ | | | |
| * = decals | ssc 916 | | | The | | Wheel bearings | v | | | |
| SC = stone chips | | | | | | Brakes | | | | |
| W = significant scuffs SC SC SC SC | | | | | | Performance | ~ | | | |
| | | Note: som | ne defects & blemishes | may not be disc | laved in the diagram | Hand Brake | ~ | | | |
| Body Insp | pection Comments | | | | | Tyres (lowest observed tread | - | oftvre | | |
| | | | | | | | | | | |
| | | | | | | Right front | | | mm | |
| | | | | | | Left rear | | 3 | mm | |
| | | | | | | Right rear | | 2 | mm | |
| Conditions During Body Inspection: Wet | | | | | | | | | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Spare Yes Yes | | | | |
| | | | | | | | | | | |
| | | | | | | Suspension performance | ~ | | | |
| | | | | | | Steering performance Shock absorbers | ~ | | | |
| | | | | | | | ~ | | | |
| | | | | | | Air Conditioning / Heater | | | | |
| Interior Comments | | | | | | Operation V | | | | |
| | | | | | | | | | | |
| Seats | 5 | | | | | Head lights | ~ | | | |
| Carpets | Average | | | | | Tail lights | ~ | | | |
| | Average | | | | | Indicators | ~ | | | |
| Panels | | | | | | Dashboard warning lights | ~ | | | |
| Dashboa | rd Average | | | | | Wipers (front & rear) | ~ | | | |
| | | | | | | Window winder FL | ~ | | | |
| General | omments | | | | | Window winder FR | ~ | | | |
| <u>General Comments</u> Does shudder when driving but does go away , | | | | | | Window winder RL | ~ | | | |
| | | | | | | Window winder RR | ~ | | | |
| | | | | | | Rear view mirrors | ~ | | | |
| | | | | | | Radio (basic test only) | ~ | | | |
| | | | | | | CD (basic test only) | ~ | | | |
| | | | | | | Number of keys | 2 | | | |
| Road Conditions During Test Drive: Wet | | | | | | Central locking | ~ | | | |
| Engine Timing Mechanism: | | | | | | Remote locking | ~ | | | |
| Engine Timing Mechanism: Unknown Evidence of Cam Belt Replacement: Not Applicable Kms: | | | | | | Sat. Nav. (basic test only) | | | ~ | |
| Evidence | oi Cam Beit Replac | ement: N | lot Applicable | Kms: | | Reversing camera | | | ~ | |
| Inspector | Inspected by: Donovan Matara Date: 19 Jul 2018 | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |

I have read and understood this condition guide.

Name:

Signature: