

Report ID: 18,282,739 Version: 2 Created: 06 Aug 2018

Make:	Mitsubishi	Model:	Outlander	Body Style:	SUV		Pass	Fail	N/A
Year:	2,013	Registration:	GZM3	Reg Expiry:	15 Aug 2018	Engine			L
WoF Expiry:	25 Jul 2019	Odometer:	97,948 Kms	Good No:	18282739	Oil level	~		
VIN:	JMFXTGF8WDZ00266	Next Service:	102000	Service Histor	y: No	Smoke & fumes	~		
						Performance	r		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.									
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	r an additional o	charge.	Coolant condition	~		
						Performance	~		
Key:		-0		-161-		Radiator / Hoses (visual)	~		
S = scratch						Transmission	-		L
D = dent	sw 6/6			The		Operation	~		
R = rust PT = paint defe				\prod		Noise	~		
C = crack						Clutch			~
P = pin dent						CV joints	~		-
* = decals	ssc 916			AL	EITR	Wheel bearings	~		
SC = stone chips						Brakes			<u> </u>
W = significant scuffs						Performance	~		
		Note: som	ne defects & blemishes	may not be disr	laved in the diagram	Hand Brake	~		
Body Insp	pection Comments	1010.3011		indy not be disp	ayea in the alagram		•	oftyre))
						Tyres (lowest observed tread depth of tyres)			
						Left front	3.	-	mm
						Right front	3.		mm
						Left rear	6		mm
Conditions During Body Inspection: Dry						Right rear	6.5 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
	inage a onder bor	meenspeede	<u>in comments</u>			Suspension			
						Suspension performance	~		
						Steering performance	~		
Shock al							~		
						Air Conditioning / Heater	1		
Interior Comments						Operation 🖌			
Good						Electrical / Accessories			
Seats	0000					Head lights	~		ļ
Carpets	Good					Tail lights	~		
	Good					Indicators	~		<u> </u>
Panels	Good					Dashboard warning lights	~		
Dashboa	Good Good					Wipers (front & rear)	~		
						Window winder FL	~		
						Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Con	ditions During Test	Central locking	~						
Road Conditions During Test Drive: Dry						Remote locking	~		
Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test of									~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Eddie Marsters Date: 25 Jul 2018									
Date: 25 Jul 2018									

I have read and understood this condition guide.

Name:

Signature: