

Basic Vehicle Condition Guide

Report ID: 18,283,037


Version:

Created: 05 Aug 2018

Make: Model: **Body Style:** Hatchback Cooper Year: 2,006 Registration: Reg Expiry: HLL508 25 May 2019 **WoF Expiry: Odometer:** 11 Jun 2019 **Good No:** 18283037 139,079 Kms VIN: WMWRE32080TJ4214 **Next Service: Service History:** 148,500

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

Engine oil leak

| Interior Comments | | | | |
|-------------------|------|--|--|--|
| Seats | Good | | | |
| Carpets | Good | | | |
| Panels | Good | | | |
| Dashboard | Good | | | |

General Comments

Excess noise from steering while turning

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Kms: Not Applicable

05 Aug 2018 Inspected by: Mathew Varghese Date:

Name:

| | Pass | Fail | N/A |
|------------------------------|--|----------|-----|
| Engine | | | |
| Oil level | ~ | | |
| Smoke & fumes | V | | |
| Performance | ~ | | |
| Noise | ~ | | |
| Cooling System | | | |
| Coolant condition | ~ | | |
| Performance | ~ | | |
| Radiator / Hoses (visual) | ~ | | |
| Transmission | | | |
| Operation | ~ | | |
| Noise | ~ | | |
| Clutch | | | ~ |
| CV joints | | | ~ |
| Wheel bearings | ~ | | |
| Brakes | | | |
| Performance | ' | | |
| Hand Brake | ~ | | |
| Tyres (lowest observed tread | d depth | of tyre | es) |
| Left front | | 2 | mm |
| Right front | | 2 | mm |
| Left rear | 4 | | mm |
| Right rear | 5 | | mm |
| Spare | | N/A | |
| Suspension | | | |
| Suspension performance | ~ | | |
| Steering performance | ~ | | |
| Shock absorbers | ~ | | |
| Air Conditioning / Heater | 1 | | - |
| Operation | ~ | | |
| Electrical / Accessories | l | | |
| Head lights | ~ | | |
| Tail lights | | | |
| Indicators | ~ | | |
| Dashboard warning lights | ~ | | |
| Wipers (front & rear) | \(\times \) \(\t | | |
| Window winder FL | ~ | | |
| Window winder FR | ~ | | |
| Window winder RL | | | ~ |
| Window winder RR | | | ~ |
| Rear view mirrors | ~ | | |
| Radio (basic test only) | ~ | | |
| CD (basic test only) | ~ | | |
| Number of keys | 1 | I | |
| Central locking | ~ | | |
| Remote locking | ~ | | |
| Sat. Nav. (basic test only) | | | ~ |
| Reversing camera | | | ~ |
| | | <u> </u> | |

Signature: