

Report ID: 18,283,435 Version: 1 17 Jul 2018 Created:

Make:	Honda	Model:	CRV	Body Style:	SUV		Pass	Fail	N/A
Year:	2,004	<b>Registration:</b>	GJG649	Reg Expiry:	14 Nov 2018	Engine	1		I
WoF Expiry:	07 Mar 2019	Odometer:	86,125 Kms	Good No:	18283435	Oil level	~		
VIN:	7AT08G7HX12001122	Next Service:	90000	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	r an additional c	harge.	Coolant condition	~		
						Performance	~		
Key:	S	-0	LS			Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission	mission		
D = dent R = rust	sc			215	HIVS	Operation	~		
PT = paint defe	ect NP	r I		$\left[ \left( \right) \right]$	70111	Noise	~		
C = crack						Clutch			~
P = pin dent	HIP				74116	CV joints	~		
* = decals	sc 916			10		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
w – signincan	SC		S			Performance	~		
Body Insr	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
body inspection comments					Tyres (lowest observed tread depth of tyres)				
					Left front	5	5	mm	
						Right front	5	5	mm
						Left rear	5	5	mm
Conditions During Body Inspection: Dry						Right rear	5 mm		
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Clean						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpots	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	<		
Dashboa	Good					Wipers (front & rear)	~		
						Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Con	ditions During Test	t Drive:	Dry			Central locking	~		
Enging Ti	ming Mechanism:	<b>T'</b>				Remote locking	~		
-	-	Timing (		Verse		Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Stuart Melbourne Date: 17 Jul 2018									

I have read and understood this condition guide.

Name: .....

Signature: .....