

Report ID: 18,285,048 Version: 1 29 Aug 2018 Created:

Make: Audi Model: A3 Body Style: Hatchback	P:	ass Fail	N/A
Make: Audi Model: A3 Body Style: Hatchback Year: 2,007 Registration: Reg Expiry: Engine	r c		
WoF Expiry: 16 Jul 2019 Odometer: 48,991 Kms Good No: 18285048 Oil leve	I v		1
	k fumes		
Perform	•		
Note: This report is not a warranty			-
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantied or	v		
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.			1
	t condition		
Key:	•		
S = scratch	or / Hoses (visual)		
D = dent			T
R = rust S 9 0 Operati			
PT = paint defect Noise	v	·	
C = crack			~
P = pin dent * = decals	ts 🖌	·	
SC = stone chips	pearings 🗸	•	
W = significant scuffs Brakes			
Perform	nance 🖌	•	
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram Hand B	rake 🖌	•	
	Tyres (lowest observed tread depth of tyres)		
Left fro	nt	5	mm
Right fr	ont	5	mm
Left rea	r	5	mm
Conditions During Body Inspection: Dry	ar	5	mm
Spare	Spare Yes		
Under Carriage & Under Bonnet Inspection Comments Suspens	ion		
Suspen	sion performance	/	1
Steerin	g performance 🖌	/	
Shock a	bsorbers 🖌	/	
Air Cond	itioning / Heater		1
Operati	-	/	1
Interior Comments	Electrical / Accessories		<u> </u>
Seats Good Head live		/	1
	, ,		
Carpets Good Indicate			
Good	ard warning lights		
Wingrs	(front & rear)		
Dashboard	v winder FL		
	-		
	v winder RR		
	ew mirrors		
	Dasic test only)		
	ic test only)		
	r of keys 2		1
Note contaitions builting rest brive. Wet	locking		<u> </u>
	e locking 🖌	·	<u> </u>
Jat. Na	/. (basic test only)		~
Evidence of Cam Belt Replacement: No Kms:	ng camera		~
Inspected by: John Lindsay Date: 29 Aug 2018			
inspected by. John Linusay Date. 29 Aug 2016			

I have read and understood this condition guide.

Name:

Signature: