

Report ID: 18,285,053 Version: 1 Created: 02 Aug 2018

Make:	Mazda	Model:	Demio	Body Style: Hatchback		Pass	Fail	N/A
Year:	2,012	Registration:	201110	Reg Expiry:	Engine			L
	,	Odometer:	108,256 Kms	Good No: 18285053	Oil level	~		
VIN:	7AT0C12HX18529102		118240	Service History: No	Smoke & fumes	~		
	7711001211710525102		110210		Performance	~		
	port is not a warranty				Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends					Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.					Coolant condition			
		_			Performance	~		
Key:		-0	s s		Radiator / Hoses (visual)	~		
S = scratch					Transmission			
D = dent B = rust SSC SPT					Operation			<u> </u>
R = rust					Noise	~ ~		
PT = paint defe C = crack	ect M				Clutch	V		
P = pin dent	Ho							~
* = decals	sc pp				CV joints	~		
SC = stone chi	ps US	VA			Wheel bearings	~		
W = significant scuffs					Brakes			T
		Nata			Performance	~		
Body Insp	pection Comments	Note: som	ie delects & blemisnes	may not be displayed in the diagram	Hand Brake		<u>.</u>	Ļ
					Tyres (lowest observed tread depth of tyres)			
					Left front	8		mm
					Right front	8		mm
					Left rear		6 mm	
Conditions During Body Inspection: Dry					Right rear	6 mm		mm
Under Carriage & Under Bonnet Inspection Comments					Spare	Yes		
	mage & onder bor	inet inspectic	<u>In comments</u>		Suspension			
					Suspension performance	~		
					Steering performance	~		-
					Shock absorbers	~		
					Air Conditioning / Heater			. <u> </u>
Interior Comments					Operation	~		
Average					Electrical / Accessories			
Seats	Average				Head lights	~		
Carpets	Average				Tail lights	~		
Carpets					Indicators	~		
Panels	Average				Dashboard warning lights	~		
Dashboa	rd Average				Wipers (front & rear)	~		
					Window winder FL	~		
	_				Window winder FR	~		
<u>General Comments</u>					Window winder RL	~		
					Window winder RR	~		
					Rear view mirrors	~		
					Radio (basic test only)	~		
					CD (basic test only)	~		
					Number of keys	1		
Road Conditions During Test Drive: Dry					Central locking	~		
			-		Remote locking	~		
					Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:	Reversing camera			~
Inspected by: John Lindsay Date: 02 Aug 2018								

I have read and understood this condition guide.

Name:

Signature: