

Report ID: 18,285,599 Version: 3 Created: 05 Sep 2018

Make:	Hyundai	Model:	120	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2,015	<b>Registration:</b>	JCD156	<b>Reg Expiry:</b>	29 Oct 2018	Engine	1		
WoF Expiry:	20 Jul 2019	Odometer:	31,934 Kms	Good No:	18285599	Oil level	~		
VIN:	MALBB51CMFM69446	Next Service:	43,000	Service Histor	<b>y:</b> Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	r an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:	S	-0	LS			Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission	1		
B = rust S A A S S S S S S S S S S S S S S S S						Operation	~		
PT = paint defect						Noise	~		
C = crack						Clutch			~
P = pin dent	HIP				7411L	CV joints	~		
*=decals						Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
						Performance	~		
Body Insr	pection Comments	Note: som	e defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
LH wing mirror cover cracked						Tyres (lowest observed tread depth of tyres)			
						Left front 5.0			mm
						Right front	3	.0	mm
						Left rear	5	.0	mm
Conditions During Body Inspection: Wet						Right rear	4.0 mr		mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
Carpote	Average					Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	Good					Wipers (front & rear)	~		
	iiu					Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors		~	
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Wet						Central locking	~		
Enging Ti	ming Mochanism	<b>T11</b>	7h - :			Remote locking	~		
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
Evidence	or Cam Beit Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Mathew Varghese Date: 23 Jul 2018									

I have read and understood this condition guide.

Name: .....

Signature: .....