

Report ID: 18,285,683 Version: 4 Created: 17 Aug 2018

Make:	Volkswagen	Model:	Amarok	Body Style:	Utility		Pass	Fail	N/A
Year:	2,014	Registration:	LMM304	Reg Expiry:	05 Oct 2018	Engine			
WoF Expiry:	03 Aug 2019	Odometer:	87,867 Kms	Good No:	18285683	Oil level	~		
VIN:	WV1ZZZ2HZEA03612	Next Service:	100,674	Service Histor		Smoke & fumes	~		
			,			Performance	~		
	port is not a warranty	avation is made	for one and miles as	Dauta hava nat	heen discontined or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
						Performance	~		
Key:		-0			s	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust	s dl			The		Operation	~		
PT = paint defe				$\left(\left \right\rangle \right)$		Noise	~		
C = crack						Clutch			~
P = pin dent	HID				74114	CV joints	~		
* = decals	sc 916			The		Wheel bearings	~		
SC = stone chips						Brakes			
W = significan	t scuffs					Performance	~		
Dadulus		Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			25)
						Left front	7.0 mm		
						Right front	7.		mm
						Left rear	7.	-	mm
Conditions During Body Inspection: Wet						Right rear	7.0 mm		mm
Conditions During Body Inspection: Wet						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			L
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
	Average					Tail lights	~		
Carpets	, weitige					Indicators	~		
Panels	Average					Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
	1					Window winder FR	~		
General Comments						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Wet							~		
			WCL			Remote locking	~		<u> </u>
Engine Ti	ming Mechanism:	Timing (Chain			Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera	~		
							ı 1		
Inspected by: Mathew Varghese Date: 12 Aug 2018									

I have read and understood this condition guide.

Name:

Signature: