

## **Basic Vehicle Condition Guide**

Report ID: 18,285,864

Version:

Engine

Oil level

Noise

Smoke & fumes

Performance

Cooling System

Left front

Right front

Left rear

Right rear

Suspension

Shock absorbers Air Conditioning / Heater

**Electrical / Accessories** 

Dashboard warning lights

Wipers (front & rear)

Window winder FL Window winder FR

Window winder RL

Window winder RR

Rear view mirrors

Radio (basic test only)

CD (basic test only)

Number of keys

Operation

Head lights Tail lights Indicators

Suspension performance Steering performance

Spare

Coolant condition

Created: 30 Jul 2018

Pass

~

~

/

1

1

Fail

N/A

mm

mm

mm

 $\mathsf{mm}$ 

1

1

9

9

9

1

/

/

1

1

~


3

Yes

Make: Model: **Body Style:** Toyota Hiace Van Year: Registration: **Reg Expiry:** 2,013 **Odometer:** WoF Expiry: **Good No:** 16 Jul 2019 112,953 Kms 18285864 VIN: 7AT0H60FX18111429 **Next Service: Service History:** 122,949kms No

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



**Conditions During Body Inspection:** Dry

**Under Carriage & Under Bonnet Inspection Comments** 

Tidy.

Interior Comments				
Seats	Average			
Carpets	Average			
Panels	Average			
Dashboard	Average			

## **General Comments**

Tidy diesel van.

**Road Conditions During Test Drive:** Dry

**Engine Timing Mechanism:** Cambelt

	Central locking	V			
	Remote locking	~			
	Sat. Nav. (basic test only)		~		
Kms:	Reversing camera		~		
Date: 30 Jul 2018					
Name: Signature:					

Engine Timing Mechanism: Cambelt Evidence of Cam Belt Replacement: No	Kms:		<b>ソ</b>
Inspected by: Daryll Timms		Date: 30 Jul 2018	
nave read and understood this condition guide.	Name:	Signature:	