

Report ID: 18,286,077 Version: 2 23 Jul 2018 Created:

Make:	Mitsubishi	Model:	Lancer	Body Style:	Sedan		Pass	Fail	N/A
Year:	2,012	<b>Registration:</b>	GPS589	<b>Reg Expiry:</b>	02 Mar 2019	Engine	1		L
WoF Expiry:	18 Dec 2018	Odometer:	93,852 Kms	Good No:	18286077	Oil level	~		
VIN:	JMFSTCY4ADU002085	Next Service:	103000	Service Histor	<b>y:</b> Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
						Performance	V		
Key:		-0	LS	-01-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
D = dent R = rust	sc			710	HIVS	Operation	~		
PT = paint defe	ect NP				101h	Noise	~		
C = crack					SC	Clutch			~
P = pin dent	HIP				74116	CV joints	V		
* = decals	sc 916			10	ED S	Wheel bearings	V		
SC = stone chips W = significant scuffs						Brakes			
						Performance	~		
Body Insr	pection Comments	Note: som	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	V		
body inspection comments						Tyres (lowest observed tread depth of tyres)			
					Left front	3	.5	mm	
						Right front	3.	.5	mm
						Left rear	3.	.0	mm
Conditions During Body Inspection: Wet						Right rear	3.	.0	mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
Carpets	Average					Tail lights	~		
						Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	rd Average					Wipers (front & rear)	~		
						Window winder FL	~		
						Window winder FR	~		
<u>General C</u>	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Wet						Central locking	~		<u> </u>
Enging Ti	ning Machanism	<b>T· ·</b> ·				Remote locking	~		<u> </u>
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
Evidence	ог сапт вен керіас	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Xinghui Lin Date: 22 Jul 2018									

I have read and understood this condition guide.

Name: .....

Signature: .....