

Report ID: 18,286,181 Version: 1 20 Jul 2018 Created:

| Make: | Hyundai | Model: | Santa FE | Body Style: | SUV | | Pass | Fail | N/A |
|--|--------------------------|-----------------|------------------------|-------------------|--------------------|--|--------|--------|-----|
| Year: | 2,007 | Registration: | DZG760 | Reg Expiry: | 24 Dec 2018 | Engine | I | 1 | 1 |
| WoF Expiry: | 20 Jun 2019 | Odometer: | 241,745 Kms | Good No: | 18286181 | Oil level | ~ | | |
| VIN: | KMHSH81WR7U21323 | Next Service: | 241904 | Service Histor | y: Yes | Smoke & fumes | ~ | | |
| | | | | | | Performance | ~ | | |
| | port is not a warranty | oration is made | for ago and miloago | Parts have not | been dismontled or | Noise | ~ | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Cooling System | | | |
| a full mechar | ical inspection prior to | purchase and t | his can be arranged fo | r an additional o | harge. | Coolant condition | ~ | | |
| | | | | | | Performance | ~ | | |
| Key: | sc | -0 | S S | | s | Radiator / Hoses (visual) | ~ | | |
| S = scratch | | | | | | Transmission | | | I |
| D = dent | | | | | | Operation | ~ | | |
| R = rust PT = paint defect | | | | | | Noise | ~ | | |
| C = crack | | | | | | Clutch | • | | ~ |
| P = pin dent | | | | | | CV joints | ~ | | - |
| * = decals S D PT SC PIP | | | | | | Wheel bearings | ~ | | |
| SC = stone chips | | | | | | Brakes | | | L |
| W = significant scuffs SC W S S | | | | | | Performance V | | | |
| Note: come defects ? blamiches may not be displayed in the displayer | | | | | | Hand Brake | ~ | | |
| body inspection comments | | | | | | | | ofture | |
| Windscreen stone chips CVA Boar loft door locking machanism poisy | | | | | | Tyres (lowest observed tread depth of tyres) | | | |
| Rear left door locking mechanism noisy | | | | | | Left front | 3. | | mm |
| | | | | | | Right front | 4. | | mm |
| | | | | | | Left rear | 4. | | mm |
| Conditions During Body Inspection: Dry | | | | | | Right rear | 5.5 mm | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Spare Yes | | | |
| | inage & onder bor | inet inspectic | <u>on comments</u> | | | Suspension | | | 1 |
| | | | | | | Suspension performance | ~ | | |
| | | | | | | Steering performance | ~ | | |
| | | | | | | Shock absorbers | ~ | | |
| | | | | | | Air Conditioning / Heater | | | |
| Interior Comments | | | | | | Operation | ~ | | |
| Average | | | | | | Electrical / Accessories | | | |
| Seats | Avelage | | | | | Head lights | ~ | | |
| Carpets | Average | | | | | Tail lights | ~ | | |
| | | | | | | Indicators | ~ | | |
| Panels | Average | | | | | Dashboard warning lights | ~ | | |
| Dashboa | Average | | | | | Wipers (front & rear) | ~ | | |
| | | | | | | Window winder FL | ~ | | |
| | | | | | | Window winder FR | ~ | | |
| General C | <u>Comments</u> | | | | | Window winder RL | ~ | | |
| | | | | | | Window winder RR | ~ | | |
| | | | | | | Rear view mirrors | ~ | | |
| | | | | | | Radio (basic test only) | ~ | | |
| | | | | | | CD (basic test only) | ~ | | |
| | | | | | | Number of keys | 2 | | |
| Road Conditions During Test Drive: Wet | | | | | | Central locking | ~ | | |
| | | | | | | Remote locking | ~ | | |
| Engine Timing Mechanism: Cambelt | | | | | | Sat. Nav. (basic test only) | | | ~ |
| Evidence of Cam Belt Replacement: No Kms: | | | | | | Reversing camera | | | ~ |
| | | | | | | | | | |
| Inspected by: Ca Thach Date: 20 Jul 2018 | | | | | | | | | |
| I have read and understood this condition guide. Name: | | | | | | | | | |