

Report ID: 18,287,223 Version: 1 Created: 25 Jul 2018

Make:	Hyundai	Model:	lmax	Body Style:	People Mover		Pass	Fail	N/A
Year:	2,014	Registration:	HMG461	Reg Expiry:	08 Aug 2018	Engine	1		I
WoF Expiry:	10 Jul 2019	Odometer:	75,440 Kms	Good No:	18287223	Oil level	~		
VIN:	KMHWH81RMEU6475	Next Service:	89,000kms	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition			
						Performance	~		
Key:		-0	PW PW		Р	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust SW						Operation	~		
PT = paint defect						Noise	~		
C = crack						Clutch			~
P = pin dent						CV joints			~
* = decals SC 919 S						Wheel bearings	~		•
SC = stone chips						Brakes			
W = significant scuffs W W S P W W D W						Performance			
Note: come defecte 8 blamiches may not be displayed in the displayer						Hand Brake	~		
body inspection comments						Tyres (lowest observed tread	-	oftvre	() ()
Arial missing. L/H roof moulding missing .						Left front		-	
Fine chips on screen .						Right front			mm
						Left rear		5	mm
						Right rear		0	
Conditions During Body Inspection: Dry							6 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes Yes			
Tidy.						· · · · · · · · · · · · · · · · · · ·			
ndy.						Suspension performance Steering performance	~		
						51	~		
						Shock absorbers	~		
						Air Conditioning / Heater			1
Interior Comments						Operation	~		
Good						Electrical / Accessories			1
Seats						Head lights	~		
Carpets	Good					Tail lights	~		
	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
						Window winder FL	~		
Concret						Window winder FR	~		
<u>General Comments</u> Good 8 seater mini van.						Window winder RL			~
						Window winder RR			~
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	10	Kms:		Reversing camera	~		
Inspected by: Daryll Timms Date: 25 Jul 2018									
I have read and understood this condition guide. Name:									