

Report ID: 18,287,366 Version: 1 Created: 01 Aug 2018

Make:	Hyundai	Model:	130	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2,011		KJL252	Reg Expiry:	13 Sep 2018	Engine			L
WoF Expiry:		Odometer:	50,126 Kms	Good No:	18287366	Oil level	~		
VIN:	KMHDC51EMCU36874	Next Service:		Service Histor		Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for ago and milaago	Darts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
						Performance	v		
Key:		-0	P SC	-161-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	sc			The		Operation	~		
R = rust				r In	JHIH	Noise	~		
PT = paint def C = crack				+		Clutch	•		~
P = pin dent						CV joints	~		
* = decals	sc qlp			AL-	EIR	Wheel bearings			
SC = stone chips						Brakes	~		
W = significant scuffs									
							v		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake		- f t wa	
					Tyres (lowest observed tread depth of tyres)				
					Left front 5			mm	
						Right front	6		mm
					Left rear	6		mm	
Conditions During Body Inspection: Dry						Right rear	6 mm		mm
Under Carriage & Under Pennet Inspection Comments						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Clean						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation	~		
Good						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	Good					Tail lights	~		
						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
Dashboa	iu					Window winder FL	~		
	-					Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lo	Kms:		Reversing camera			~
						L			
Inspected by: Stuart Melbourne Date: 01 Aug 2018									
I have read and understood this condition guide. Name:									