

Report ID: 18,288,520 Version: 1 20 Jul 2018 Created:

| Make: | Hyundai | Model: | lx35 | Body Style: | SUV | | Pass | Fail | N/A |
|--|---|----------------------|------------------------|--------------------|----------------------|--|------|------|-----|
| Year: | 2,011 | Registration: | GDH109 | Reg Expiry: | 27 Nov 2018 | Engine | | | |
| WoF Expiry: | 29 Dec 2018 | Odometer: | 170,778 Kms | Good No: | 18288520 | Oil level | ~ | | |
| VIN: | KMHJU81VSCU37972₄ | Next Service: | 180600 | Service Histor | y: No | Smoke & fumes | V | | |
| | | | | | | Performance | V | | |
| | port is not a warranty a guide only. Conside | eration is made | for age and mileage | . Parts have not | been dismantled or | Noise | ~ | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Cooling System | | | |
| a full mechar | lical inspection prior to | purchase and th | his can be arranged to | r an additional o | narge. | Coolant condition | ~ | | |
| | S W | | S* SD | | S D | Performance | ~ | | |
| Key: | | | | 500- | 30 | Radiator / Hoses (visual) | ~ | | |
| S = scratch D = dent | | | | | | Transmission | | | |
| R = rust | s sc | | | 210 | HIVS | Operation | ~ | | |
| PT = paint def | ect NP | | | | 17111 | Noise | ~ | | |
| C = crack | | | | | S R SC | Clutch | | | ~ |
| P = pin dent | I DEC HIP | | | | 74116 | CV joints | ~ | | |
| * = decals | SDSC 91 | 10 | | 10 | .EID · · · · · · | Wheel bearings | ~ | | |
| SC = stone chips | | | | | | Brakes | | | |
| W = significant scuffs S S D * S W S | | | | | | Performance | ~ | | |
| Body Inc | pection Comments | Note: som | ne defects & blemishes | may not be disp | layed in the diagram | Hand Brake | r | | |
| body inspection comments | | | | | | Tyres (lowest observed tread depth of tyres) | | | es) |
| | | | | | | Left front 6 | | | mm |
| | | | | | | Right front | | 7 | mm |
| | | | | | | Left rear | | 5 | mm |
| Conditions During Body Inspection: Wet | | | | | | Right rear | | 5 | mm |
| | | | | | | Spare Yes | | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Suspension | 1 | | |
| Oil leak | | | | | | Suspension performance | ~ | | |
| | | | | | | Steering performance | r | | |
| | | | | | | Shock absorbers | r | | |
| | | | | | | Air Conditioning / Heater | 1 | I | 1 |
| | | | | | | Operation 🖌 | | | |
| Interior Comments | | | | | | Electrical / Accessories | | | |
| Seats | Hole in dri | vers seat | | | | Head lights | ~ | | |
| | Average | | | | | Tail lights | ~ | | |
| Carpets | | | | | | Indicators | ~ | | |
| Panels | Average | | | | | Dashboard warning lights | ~ | | |
| | . Scratches | on dashboard an | nd centre console | | | Wipers (front & rear) | ~ | | |
| Dashboa | rd | | | | | Window winder FL | ~ | | |
| | | | | | | Window winder FR | ~ | | |
| General Comments | | | | | | Window winder RL | ~ | | |
| | | | | | | Window winder RR | ~ | | |
| | | | | | | Rear view mirrors | ~ | | |
| | | | | | | Radio (basic test only) | ~ | | |
| | | | | | | CD (basic test only) | ~ | | |
| | | | | | | Number of keys | 2 | | |
| Road Conditions During Test Drive: Wet | | | | | | Central locking | ~ | | |
| | | | | | | Remote locking | ~ | | |
| Engine Timing Mechanism: Timing Chain | | | | | | Sat. Nav. (basic test only) | | | ~ |
| Evidence | of Cam Belt Replac | ement: N | lot Applicable | Kms: | | Reversing camera | | | ~ |
| | | | | | | | | | |
| Inspected by: John Lindsay Date: 20 Jul 2018 | | | | | | | | | |
| | | | | | | | | | |

I have read and understood this condition guide.

Name:

Signature: