

Basic Vehicle Condition Guide

Report ID: 18,288,772


Version: 1

Created: 20 Jul 2018

Make: Model: Hyundai XG **Body Style:** Sedan Year: 2,004 Registration: GBH920 Reg Expiry: 08 Nov 2018 WoF Expiry: **Odometer:** 28 Nov 2018 **Good No:** 18288772 174,735 Kms VIN: KMHFU41DR5A38111 **Next Service: Service History:** No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Left rear door roof chrome rubber. Right rear door roof chrome dent.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

FWD.

<u>Interior Comments</u>			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good n dash cover loose.		

General Comments

Inspected by:

Roof linning loose. Engine oil level on low mark.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: Yes Kms: 9

Kms: 91,000

	Pass	Fail	N/A	
Engine				
Oil level	~			
Smoke & fumes	~			
Performance	\(\triangle \)			
Noise	~			
Cooling System				
Coolant condition	~			
Performance	٧ ٧			
Radiator / Hoses (visual)	~			
Transmission				
Operation	~			
Noise	~			
Clutch			~	
CV joints	~			
Wheel bearings	~			
Brakes			•	
Performance	~			
Hand Brake	~			
Tyres (lowest observed tread depth of tyres)				
Left front	5	.5	mm	
Right front	5	.5	mm	
Left rear	6	.5	mm	
Right rear	6.5		mm	
Spare		Yes		
Suspension				
Suspension performance	~			
Steering performance	~			
Shock absorbers	~			
Air Conditioning / Heater				
Operation	~			
Electrical / Accessories				
Head lights		~		
Tail lights	~			
Indicators				
Dashboard warning lights	V V			
Wipers (front & rear)				
Window winder FL	> > > >			
Window winder FR	~			
Window winder RL	~			
Window winder RR	~			
Rear view mirrors	~			
Radio (basic test only)	~			
CD (basic test only)	~			
Number of keys	2			
Central locking	·			
Remote locking			~	
Sat. Nav. (basic test only)			- V	
Reversing camera			<i>y</i>	
eversing cumeru				

I have read and understood this condition guide.

Eddie Marsters

Name:

Signature:

20 Jul 2018

Date: