

Report ID: 18,288,971 Version: 1 23 Jul 2018 Created:

Make:	Toyota	Model:	Vitz	Body Style:	Hatchback		Pass	Fail	N/A	
Year:	2,001	<b>Registration:</b>	EMK549	<b>Reg Expiry:</b>	16 Aug 2018	Engine	I	1	4	
WoF Expiry:	22 Sep 2018	Odometer:	215,700 Kms	Good No:	18288971	Oil level	~			
VIN:	7A8H63E0708009280	Next Service:		Service Histor	<b>y:</b> No	Smoke & fumes	~			
						Performance	~		<u> </u>	
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismantled or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechan	ical inspection prior to	purchase and tl	nis can be arranged fo	r an additional o	harge.	Coolant condition	~		1	
						Performance	· ·			
Key:	P	-0	S P	-161-	S D	Radiator / Hoses (visua				
S = scratch						Transmission	,		<u> </u>	
D = dent	s sc			The	EID S	Operation	~		1	
R = rust PT = paint defe				$\prod$	JHIH	Noise	· ·			
C = crack				+	R SC	Clutch	· ·			
P = pin dent	Ho					CV joints				
* = decals	sc 916			AL.	EII P	Wheel bearings	- V			
SC = stone chips							Brakes			
W = significant scuffs S D W S S D W D						Performance	<b>v</b>		1	
		Nataron	ne defects & blemishes			Hand Brake	V			
Body Insp	pection Comments	Note. son	le délects & blemisnes	illiay not be disp	layed in the diagram		-			
						Tyres (lowest observed tread depth of tyres)				
						Left front		6	mm	
						Right front		6	mm	
						Left rear		3	mm	
Conditions During Body Inspection: Dry									mm	
Under Carriage & Under Bonnet Inspection Comments						Spare Yes				
Under Ca	rrlage & Under Bor	inet inspectio	on Comments			Suspension		1		
						Suspension performa	nce 🖌			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Hea	ter			
						Operation	~			
Interior Comments						Electrical / Accessories				
Seats	Average					Head lights	~			
	Average					Tail lights	~			
Carpets						Indicators	~			
Panels	Average					Dashboard warning lig	ghts 🖌		1	
	Average					Wipers (front & rear)	~		1	
Dashboa	rd					Window winder FL	~		+	
	I					Window winder FR	· ·		+	
General Comments						Window winder RL	· ·		+	
Both rear headrests missing						Window winder RR	· ·		+	
кight rear e	exterior door handle loo	se				Rear view mirrors	· ·		+	
						Radio (basic test only)			+	
						CD (basic test only)			+	
						Number of keys	1		<u> </u>	
Deed Conditions Duving Test Driver -						Central locking	· · ·		1	
Road Conditions During Test Drive: Dry						Remote locking		~	+	
Engine Tir	ming Mechanism:	Timing	Chain			Sat. Nav. (basic test or		~		
Evidence of Cam Belt Replacement: Not Applicable Kms:							iy)		V 	
						Reversing camera			~	
Inspected by: John Lindsay Date: 23 Jul 20										

I have read and understood this condition guide.

Name: .....

Signature: .....