

## **Basic Vehicle Condition Guide**

Report ID: 18,289,029

Version:

**Engine** 

Created: 23 Jul 2018


N/A

Fail

Make: Model: Celica **Body Style:** Hatchback Toyota Year: 1,996 Registration: Reg Expiry: **ABA887** 07 Nov 2018 WoF Expiry: **Odometer:** 30 Nov 2018 **Good No:** 18289029 231,769 Kms VIN: 7A8H6030701102891 **Next Service: Service History:** 238740 No

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



## **Body Inspection Comments**

Minor stone chips in the windscreen, spoiler cracked,

**Conditions During Body Inspection:** Wet

**Under Carriage & Under Bonnet Inspection Comments** 

<u>Interior Comments</u>				
Seats	drivers seat ripped ,			
Carpets	Average			
Panels	Average			
Dashboard	Average			

## **General Comments**

Inspected by:

Road Conditions During Test Drive: Wet

**Engine Timing Mechanism:** Cambelt

**Evidence of Cam Belt Replacement:** Yes

Kms: 190,409

Oil level			
Smoke & fumes	v v		
Performance	~		
Noise	~		
Cooling System		•	
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission		•	
Operation	~		
Noise	\( \times \)		
Clutch	>		
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	depth	of tyre	es)
Left front	(	5	mm
Right front	7		mm
Left rear	3		mm
Right rear	3 m		mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	<i>V</i>		
Shock absorbers	~		
Air Conditioning / Heater			
Operation		~	
Electrical / Accessories		Т	
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	V V		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	~		
Window winder RL			~
Window winder RR			~
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	2		
Central locking	~		
Remote locking		~	
Sat. Nav. (basic test only)		l	<b>'</b>

I have read and understood this condition guide.

Donovan Matara

Name:			

23 Jul 2018

1

Reversing camera