

Report ID: 18,289,265 Version: 1 19 Jul 2018 Created:

Make:	Suzuki	Model:	SX4	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2,013	Registration:	GTE918	Reg Expiry:	10 Jul 2019	Engine	1		
WoF Expiry:	04 May 2019	Odometer:	139,097 Kms	Good No:	18289265	Oil level	~		
VIN:	JSAGYB51S00400469	Next Service:	150000	Service Histor	V: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismontled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	or an additional c	harge.	Coolant condition	~		
						Performance	~		
Key:	S SC	-0	s sc	-01-	SP	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	s sc			715	HIL S	Operation	~		
R = rust PT = paint def				$\left(\left \right\rangle \right)$		Noise	~		
C = crack					SC	Clutch	-		~
P = pin dent	-110				741L	CV joints	~		
* = decals	sc 916			-NL	ETTP S	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S SC S S S						Performance	~		
		Note: som	ne defects & blemishes	may not be disp	laved in the diagram	Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Tyres (lowest observed tread	-	of tyre	25)
Paint coming off grille. Stonechips on windscreen. Small hole in dash by RH vent. Cargo barrier fitted. Remote locking not working.									mm
		5	5	5		Right front		.9 }	 mm
						Left rear			mm
Conditions During Rody Inspection:						Right rear		3 mn 3 mn	
Conditions During Body Inspection: Wet						Spare			
Under Carriage & Under Bonnet Inspection Comments					Spare Yes Suspension				
Engine spla	sh guard missing.					Suspension performance	~		
	oar bushes are worn.					Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
50005						Tail lights	~		
Carpets	Average					Indicators	~		
Panels	Average					Dashboard warning lights	~		
raneis						Wipers (front & rear)	~		
Dashboa	rd Average					Window winder FL	~		
	I					Window winder FR	~		
<u>Gen</u> eral (<u>Comments</u>					Window winder RL	~		
Drives ok.					Window winder RR	~			
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		<u> </u>
Read Conditions During Test Driver						Central locking	· · · · · · · · · · · · · · · · · · ·		
Road Conditions During Test Drive: Dry						Remote locking	-	~	
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)		•	~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
	-1								
Inspected by: Roger King Date: 19 Jul 2018									

I have read and understood this condition guide.

Name:

Signature: